COPIES RECEIVED TRIBUTION FE FE U.S.G.S. LAND OFFICE OPERATOR OPERATOR	NEW MEXICO OIL CON	SERVATION COMMISSION	Form C-103 Supersedes Old C-102 and C-103 Effective 1-1-65 Sa. Indicate Type of Lease State Free X S. State Oll & Gas Lease No.
(DO NOT USE THIS FORM FOR PI USE "APPLICA	RY NOTICES AND REPORTS ON ROPOSALS TO DRILL OR TO DEEPEN OR PLUG ITION FOR PERMIT -" (FORM C-101) FOR SU	I WELLS BACK TO A DIFFERENT RESERVOIR. CH PROPOSALS.)	
OIL GAS WELL	отнел- 011 - 011 Dua	.1	7, Unit Agreement Name
2. Name of Operator	8, Farm of Lease Name		
Gulf Oil Corporation			Eubank
3. Address of Operator			9. Well No.
Box 670, Hobbs, New Mexico 88240			2
4. Location of Well			10. Field and Pool, or Wildcat
UNIT LETTER	660 FEET FROM THE North	LINE AND 660 FEET F	Blinebry & Drinkard
THE East LINE, SECT	10N 22 TOWNSHIP 21-	S RANGE 37-E NM	
15. Elevation (Show whether DF, RT, GR, etc.)			12. County
		3412' GL	Lea
16. Check	Appropriate Box To Indicate 1	Nature of Notice Report or	
Check Appropriate Box To Indicate Nature of Notice, Report or Otl NOTICE OF INTENTION TO: SUBSEQUENT			ENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
PULL OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JOB	
other Plug back, perf 1	higher in Drk, acidize	OTHER	
both zones and frac			
17. Describe Proposed or Completed O work) SEE RULE 1103.	perations (Clearly state all pertinent det	ails, and give pertinent dates, includ	ling estimated date of starting any proposed
· · · •			

6614' TD.

Pull producing equipment. Clean out to approximately 6550'. Set CI BP at approximately 6535' and cap with 10' cement, abandoning Drinkard open hole interval 6550' to 6614'. Perforate Drinkard zone in 7" casing with 2, .72" JHPF in the approximate interval 6360' to 6474'. Run treating equipment. Test BP with 3000#. Treat new perforations with 2000 gallons of 15% NE acid and frac treat with 28,000 gallons of gel brine water containing 0 to 2# SPG. Pull treating equipment. Set Baker Model D packer at approximately 6300'. Run treating equipment and treat Blinebry perforations 5734' to 5871' with 3000 gallons of 15% NE HCL acid. Flush with 1300 gallons of treated water. Pull treating equipment. Run long string of 2-3/8" OD tubing and parallel anchor. Latch into Baker Model D packer at 6300'with 12,000# tension with parallel anchor. Swab and clean up and return both zones to production. Tor Drinker 6302' Drinker 6300' Drinker 6300' Drinker 6302' Drinker 6300' Drinker 6302' Drinker 6300' Drinker 6300'

18. I hereby certify that the information above is true and complet SIGNED	te to the best of my knowledge and belief.	DATE May 3, 1974
APPROVED BY JOE Disc. 1987	TITLE	DATE