

Submit 3 Copies
to Appropriate
District Office

2

State of New Mexico
Energy, Minerals and Natural Resources Department
OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

Form C-103
Revised 1-1-89

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Drawer Dd, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, Nm 87410

API NO. (assigned by OCD on New Wells) 30-025-06734 ✓	
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input checked="" type="checkbox"/>	
6. State Oil & Gas Lease No. N/A	
7. Lease Name or Unit Agreement Name EJBANK	
8. Well No. 8	
9. Pool name or Wildcat TUBB	
10. Elevation(Show whether DF, RKB, RT, GR, etc.) 3425' GR	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator CHEVRON U.S.A. INC.	
3. Address of Operator P.O. BOX 1150 MIDLAND, TX 79702 ATTN: NITA RICE	
4. Well Location Unit Letter G : 1750 Feet From The NORTH Line and 2310 Feet From The EAST Line Section 22 Township 21S Range 37E NMPM LEA County	
10. Elevation(Show whether DF, RKB, RT, GR, etc.) 3425' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER: <input type="checkbox"/>
SUBSEQUENT REPORT OF:	
REMEDIAL WORK <input type="checkbox"/>	ALTER CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABAN. <input type="checkbox"/>
CASING TEST AND CMT JOB <input type="checkbox"/>	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations(Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

WE PROPOSE TO PLUG AND ABANDON THIS WELLBORE AS FOLLOWS:
(TD @ 7520', 5-1/2" CASING @ 7519, 8-5/8" CASING @ 2799', 13-3/8" CASING @ 315')
ND WH, NU BOP, CUT 5-1/2" CASING @ 5000' & PULL. SET CIBP @ 6300' & PUT 30 SX
PLUG ON TOP 6000-6300, ABOVE DRINKARD PERFS @ 6376-6446'. PLACE 60 SX
PLUG FROM 4900-5100', PLACE 20 SX PLUG 2650-2700' & TAG. PLACE 50 SX PLUG 150 TO SURFACE. PULL DEAD MAN ANCHORS, FILL PITS, LEVEL LOCATION
PLACE P&A MARKER AND CHANGE STATUS OF WELL TO PLUGGED AND ABANDONED

13 3/8 shoe plug 265-365

I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
SIGNATURE <i>Nita Rice</i>	TITLE TECHNICAL ASSISTANT
DATE: 3/4/93	
TYPE OR PRINT NAME NITA RICE	
TELEPHONE NO. (915)687-7436	
APPROVED BY <i>Paul Kautz</i> Geologist	
DATE MAR 08 1993	
CONDITIONS OF APPROVAL, IF ANY:	