

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.
7. Unit Agreement Name
8. Farm or Lease Name Stephens Estate
9. Well No. 1
10. Field and Pool, or Wildcat Wantz Abo
12. County Lea

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator Mobil Oil Corporation
3. Address of Operator Three Greenway Plaza East, Suite 800, Houston, Texas 77046
4. Location of Well UNIT LETTER <u>L</u> <u>1980</u> FEET FROM THE <u>South</u> LINE AND <u>660</u> FEET FROM THE <u>West</u> LINE, SECTION <u>24</u> TOWNSHIP <u>21S</u> RANGE <u>37E</u> NMPM.
15. Elevation (Show whether DF, RT, GR, etc.)

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) Pull Rods , Pump and tubing
- 2) Set cast iron birdge plug on wireline @ 6875'+, (Abo perfs 6919'-7198').
- 3) Run tubing in the hole open ended and spot a 35' Class "C" Neat cement plug on bridge plug, (= 5 sx).
- 4) Wait on cement.
- 5) Run production tubing and tag cement plug to check PBTD.
- 6) Hang off production tubing, run pump and rods, turn well over to production. (See end of tbg @ = 6771' and tbg anchor @ = 6454'for production Drinkard).

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED L.W. DuBose TITLE Authorized Agent DATE April 5, 1978

APPROVED BY _____ TITLE _____ DATE 1978

CONDITIONS OF APPROVAL, IF ANY:

1-78

RECEIVED

APR 10 1978

OIL CONSERVATION COMM.
HORRS. N. M.