NUMBER OF COPIES RECEIVES						
10	STRIBUT	IÓN				
SANTA FE	\top					
FILE						
U. S. G. S	1					
LAND OFFICE		1				
TRANSPORTER	OIL					
	GAS					
PROBATION OFFI	CE					
00584700		1				

NEW MEXICO OIL CONSERVATION COMMISSION Santa Fe, New Mexico

PROBATION OFFICE OPERATOR		MISCELLANI	EOUS N	OTIC	ES.	477		
returned to the sender on windor agent, of the plan submitted	on will be giv	strict Office, Oil Conser on the approval, with an	y modification	ns consider	red advisable, or th	e rejection by tl	he Commission	
tional instructions in the Rules	and Regulat	ions of the Commission. Indicate Nature of N				•		
		21.01.00.00.1.00.00.00.00.00.00.00.00.00.						
Notice of Intention Notice of Intention Temporarily Aband				Notice of Intention to Drill Deeper				
Notice of Intention to Plug Well		Notice of Intention to Plug Back		Х	Notice of Intention to Set Liner			
Notice of Intention Notice of Intention to Squeeze To Acidize		4	x	Notice of Intention to Shoot (Nitro)				
Notice of Intention X To Gun Perforate X		Notice of Intention (Other) Sand Fi	Notice of Intention (Other) Sand Frac			TION)N	
OIL CONSERVATION COM	MISSION	Pa		Marrice	. 1	anname 21	1062	
SANTA FE, NEW MEXICO		ISON.	WELL, NEW (Place)	Mexico	o J	(Date)	1903	
Gentlemen:								
Following is a Notice of	Intention to d	lo certain work as describ	ped below at	the				
She	11 Oil Co	mpany	State	(Sec.1	Well No.	in	H	
She (Com SE /4 NE /4 o (40-acre Subdivision) Lea	f Sec	, T. 2 15	R. 37E	.,NMPM.,	Drinkard/	Blinebry	Pool	
	FU: (FOLLO)	LL DETAILS OF PR	THE RULE	S AND R	REGULATIONS)			
PROPOSED OPERATION: . Kill Blinebry zo		Drinkard, conve	rt Blinet	ry (ga	s) to Blineb	y (oil).		
2. Kill Drinkard w/ 6594' - 6641'.	oil. Spo	ot 300 gallons g	el X-820	down to	ubing to bloc	ek open ho)le	
. Pull tubing. Dr	op Baker	CI trip bob on	top of pe	cker,	cap $w/2 sx$.	ement.		
Run GR/N log fro Derforate select	ive inter	rvals from 5760'	- 58301	using	3/8" jet shot	ts.		
Run 3" frac tubi	ng w/FRR	. set FBRC at +	5740'.	Treat:	new perforati	lons w/2000) gallons :	
acid using ball Mark II Adomite	per galle	on.					iu anu i/ a	
7. Pull 3" tubing a	nd packer	r. Check for sa	nd fill,	clean	out if necess	ary.	_	
Run 2" tubing w/ Set packer at ±	packer a	nd side door cho	ke assemi	oly w/s	traight throu	igh tool in	ı place.	
9. Swab test and pl		roduction.						
Approved		, 19		Shell Oil Company company or Oppressinal Signed By				
			Ву	R. A. I	owery I	A. LOWEI	3.Y	
A			Position	Distric	t Exploitations re	on Enginee:	<u>r</u>	
Approved OIL CONSERVATION CO	MMISSION			send	Communications re	garding wen to:		
Ву			Name	3hell 0	il Company		••••	

Address P. O. Box 1858, Roswell, New Mexico