Submit 3 Copies to Appropriate District Office

## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 **Revised 1-1-89** 

ATT TO SOME

- DATE -

DISTRICT I P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION P.O. Box 2088

WELL API NO. 30-025-09922

DISTRICT II P.O. Drawer DD, Artesia, NM 88210  Santa Fe, New Mexico 87504-2088		. 00704.0000		
		uco 87504-2088	5. Indicate Type of Lease STATE FEE	
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil & Gas Lease No.	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			. <i>((((((((((((((((((((((((((((((((((((</i>	
	PROPOSALS TO DRILL OR TO DEE ERVOIR, USE "APPLICATION FO		7. Lease Name or Unit Agreement Name	
	C-101) FOR SUCH PROPOSALS.)		W. E. LEE	
1. Type of Well: OL GAS WELL WELL	_			
WELL WELL 2. Name of Operator	OTHER		8. Well No.	
CAMPRELL & HEDRICK			3	
3. Address of Operator			9. Pool name or Wildcat	
P. O. BOX 401, MIDLAND, TEXAS 79702			DRINKARD	
4. Well Location	NO NODEL	10	ON _ WEST	
Unit LetterC : _81	Feet From The NORTH	Line and	80 Feet From The WEST Line	
Section 20	Township 21S	Range 37E	NMPM LEA County	
	10. Elevation (Show wh	nether DF, RKB, RT, GR, etc.)		
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data				
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING	
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILL	LING OPNS. PLUG AND ABANDONMENT	
PULL OR ALTER CASING		CASING TEST AND	CASING TEST AND CEMENT JOB	
		RECON	OTHER: RECOMPLETE IN TUBBS	
OTHER:		UINER.		
<ol> <li>Describe Proposed or Completed Opwork) SEE RULE 1103.</li> </ol>	crations (Clearly state all pertinent desc	sils, and give pertinent dates, i	including estimated date of starting any proposed	
4/4/2001 Kill well with KCl water. Pull tubing. Install BOP. Run tbg.				
with retrevable bridge kplug and set at 6446 GL. Load csg and test 500 psi				
			500 gal 15% acid. Swab and t	
Set tbg plug in	bridge plug at 6	446. Pull tul	oing and perforate gross	
intervals 6130-	6441, 25 holes.			
			2500 gal 15% acid. Swab flu	
and spent acid down packer. R	water. Unseat pa un tubing to 6400	cker at 5992. . Swab to cl	Trip out of hole to lay ean up. complete 4/10/01	
I hereby certify that the information above is				
SIGNATURE	Hidrick	me_OPERATOR	DATE 04/17/01	
·		· · · · · · · · · · · · · · · · · · ·	TELEPHONE NO.	
TYPE OR PRINT NAME			ELEPHONE NO.	

TILE -

(This space for State Use)

APTROVED BY --

