	ES RECEIVE	HANBER OF COPIL
	TRIBUTION	019
		SANTA FE
		FILE
 		U.S.G.S.
 		LAND OFFICE
 	OIL	
l l	GAS	TRANSPORTER
 	CE	PRORATION OFFIC
 		OPERATOR
	GAS	U.S.G.S. LAND OFFICE TRANSPORTER PRORATION OFFIC

By.

Title.....

/

ŧ, à.

EW MEXICO OIL CONSERVATION COMMISSION

Santa Fe, New Mexico

MISCELLANEOUS NOTICES

strict Office, Oil Conservation Commission, before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

Indianta Nature of Nation by Checking Relay

NOTICE OF INTENTION TO CHANGE PLANS	Notice of Intention to Temporarily Abandon Well	Nutice of Intention to Drill Deeper	
NOTICE OF INTENTION TO Plug Well	Notice of Intention to Plug Back	NUTICE OF INTENTION TO SET LINER	
Notice of Intention to Squeeze	Notice of Intention to Acidize	Nettice of Intention to Shoot (Nitro)	
Notice of Intention to Gun Perforate	Notice of Intention (Other)	Netice of Intention (Cther)	
OIL CON <mark>servation Commission</mark> Santa Fe, New Mexico	Roswell, New Maxico	March 22, 196	63
	(Place)	(Date)	
Gentlemen:			
Following is a Notice of Intention to de	o certain work as described below at the		
Shell Oil Company NW NW (Company or Operator 22 (40-acre Subdivision)	any Argo "A"		D
(Company or Operator	^{r)} 218 17% •	Drinkerd-Tibb	(Unit)
	, T, R, NN	IPM.,	Pool
(FOLLOW OPOSED OPERATION: Abandon) Kill:Tubb Gas w/oil. Kill	l Drinkard v/oil.	ND REGULATIONS) b Gas w/Blinebry (Oil).	
(FOLLOW Abandon 1 Kill: Tubb Gas w/oil. Kill Spot 300 gallons gel X-820 Pull tubing. Drop Baker (Run GR/N log from PBTD to expendable plug in place. Test 5 1/2" casing w/4000 Perforate Blinebry selecti Run 2" tubing w/BRC. Treat Treat via 5 1/2" casing w/ Bleed off pressure, run 2" Circulate sand off product Run production tubing w/up	/ INSTRUCTIONS IN THE RULES A Drinkard, dual existing Tub 1 Drinkard w/oil. 2 down tubing to block Drin 2500'. Set Baker Model "D Cap w/10' sand. psi for 30 minutes. Ively w/ 3/8" JS from appro at Blinebry w/3000 gallons /20,000 gallons lease crude ' tubing, check for sand fi tion packer, pull 2" tubing oper packer (Model M snap se	ND REGULATIONS) b Gas w/Blinebry (Oil). kard perforations 6510' - 6 ction packer at 6460'. Cap " production packer at 5950 ximately 5725' - 5880'. 15% MEA. Swab Test. Pull + 1# sund & 1/20# Mark II 11, and swab test.	w/cement. 'with 2"tubing. Adomite/ga
(FOLLOW Abandon 1 Kill: Tubb Gas w/oil. Kill: Spot 300 gallons gel X-820 Pull tubing. Drop Baker (Run GR/N log from PBTD to expendable plug in place. Test 5 1/2" casing w/4000 Perforate Blinebry selecti Run 2" tubing w/BRC. Treat Treat via 5 1/2" casing w/ Bleed off pressure, run 2" Circulate sand off product Run production tubing w/up expendable plug out of Mod	/ INSTRUCTIONS IN THE RULES A Drinkard, dual existing Tub 1 Drinkard w/oil. 2 down tubing to block Drin 2500'. Set Baker Model "D Cap w/10' sand. psi for 30 minutes. Ively w/ 3/8" JS from appro at Blinebry w/3000 gallons /20,000 gallons lease crude ' tubing, check for sand fi tion packer, pull 2" tubing oper packer (Model M snap se	ND REGULATIONS) b Gas w/Blinebry (Oil). kard perforations 6510' - 6 ction packer at 6460'. Cap " production packer at 5950 ximately 5725' - 5880'. 15% MEA. Swab Test. Pull + 1# sund & 1/20# Mark II 11, and swab test. et) and dual equipment, pun	w/cement. 'with 2"tubing. Adomite/ga
(FOLLOW Abandon 1 Kill: Tubb Gas w/oil. Kill Spot 300 gallons gel X-820 Pull tubing. Drop Baker (Run GR/N log from PBTD to expendable plug in place. Test 5 1/2" casing w/4000 Perforate Blinebry selecti Run 2" tubing w/BRC. Treat Treat via 5 1/2" casing w/ Bleed off pressure, run 2" Circulate sand off product Run production tubing w/up expendable plug out of Mod Set upper packer, swab off	/ INSTRUCTIONS IN THE RULES A Drinkard, dual existing Tub 1 Drinkard w/oil. 2 down tubing to block Drin 2500'. Set Baker Model "D Cap w/10' sand. psi for 30 minutes. Ively w/ 3/8" JS from appro- at Blinebry w/3000 gallons (20,000 gallons lease crude 'tubing, check for sand fi tion packer, pull 2" tubing oper packer (Model M snap so lel D packer.	ND REGULATIONS) b Gas w/Blinebry (Oil). kard perforations 6510' - 6 ction packer at 6460'. Cap " production packer at 5950 ximately 5725' - 5880'. 15% NEA. Swab Test. Pull + 1# sund & 1/20# Mark II 11, and swab test. et) and dual equipment, pun lace on production.	w/cement. 'with 2"tubing. Adomite/ga
(FOLLOW Abandon 1 Kill: Tubb Gas w/oil. Kill: Spot 300 gallons gel X-820 Pull tubing. Drop Baker (Run GR/N log from PBTD to expendable plug in place. Test 5 1/2" casing w/4000 Perforate Blinebry selecti Run 2" tubing w/BRC. Treat Treat via 5 1/2" casing w/ Bleed off pressure, run 2" Circulate sand off product Run production tubing w/up expendable plug out of Mod	/ INSTRUCTIONS IN THE RULES A Drinkard, dual existing Tub 1 Drinkard w/oil. 2 down tubing to block Drin 2500'. Set Baker Model "D Cap w/10' sand. psi for 30 minutes. Ively w/ 3/8" JS from appro- at Blinebry w/3000 gallons (20,000 gallons lease crude 'tubing, check for sand fi tion packer, pull 2" tubing oper packer (Model M snap so lel D packer.	ND REGULATIONS) b Gas w/Blinebry (Oil). kard perforations 6510' - 6 ction packer at 6460'. Cap " production packer at 5950 ximately 5725' - 5880'. 15% NEA. Swab Test. Pull + 1# sund & 1/20# Mark II 11, and swab test. et) and dual equipment, pun lace on production. hell Oil Company Company or Operator	w/cement. with 2" tubing. Adomite/ga
(FOLLOW Abandon 1 Kill: Tubb Gas w/oil. Kill Spot 300 gallons gel X-820 Pull tubing. Drop Baker (Run GR/N log from PBTD to expendable plug in place. Test 5 1/2" casing w/4000 Perforate Blinebry selecti Run 2" tubing w/BRC. Treat Treat via 5 1/2" casing w/ Bleed off pressure, run 2" Circulate sand off product Run production tubing w/up expendable plug out of Mod Set upper packer, swab off	/ INSTRUCTIONS IN THE RULES A Drinkard, dual existing Tub I Drinkard w/oil. D down tubing to block Drin CI trip bob on top of produ 2500'. Set Baker Model "D Cap w/10' sand. psi for 30 minutes. ively w/ 3/8" JS from appro at Blinebry w/3000 gallons /20,000 gallons lease crude ' tubing, check for sand fi tion packer, pull 2" tubing oper packer (Model M snap se lel D packer. " both Blinebry and Tubb, p. 	ND REGULATIONS) b Gas w/Blinebry (0il). kard perforations 6510' - 6 ction packer at 6460'. Cap " production packer at 5950 ximately 5725' - 5880'. 15% NEA. Swab Test. Pull + 1# sund & 1/20# Mark II 11, and swab test. et) and dual equipment, pun lace on production. hell 0il Company Company or Operator	w/cement. with 2" tubing. Adomite/ga
(FOLLOW Abandon 1 Kill: Tubb Gas w/oil. Kill Spot 300 gallons gel X-820 Pull tubing. Drop Baker (Run GR/N log from PBTD to expendable plug in place. Test 5 1/2" casing w/4000 Perforate Blinebry selecti Run 2" tubing w/BRC. Treat Treat via 5 1/2" casing w/ Bleed off pressure, run 2" Circulate sand off product Run production tubing w/up expendable plug out of Mod Set upper packer, swab off	/ INSTRUCTIONS IN THE RULES A Drinkard, dual existing Tub I Drinkard w/oil. D down tubing to block Drin CI trip bob on top of produ 2500'. Set Baker Model "D Cap w/10' sand. psi for 30 minutes. Ively w/ 3/8" JS from appro- at Blinebry w/3000 gallons /20,000 gallons lease crude ' tubing, check for sand fi tion packer, pull 2" tubing oper packer (Model M snap so lel D packer. ' both Blinebry and Tubb, p. 	ND REGULATIONS) b Gas w/Blinebry (Oil). kard perforations 6510' - 6 ction packer at 6460'. Cap " production packer at 5950 ximately 5725' - 5880'. 15% NEA. Swab Test. Pull + 1# sund & 1/20# Mark II 11, and swab test. et) and dual equipment, pun lace on production. hell Oil Company Company or Operator	v/cement. v with 2" tubing. Adomite/ga

Name Shell Oil Company

P. O. Box 1858, Roswell, New Mexico Address