

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator <i>Humble Oil & Refg Co.</i>	8. Farm or Lease Name <i>Blinberry Oil Com #1</i>
3. Address of Operator <i>Box 1600- Midland, Texas 79701</i>	9. Well No. <i>1</i>
4. Location of Well UNIT LETTER <i>C</i> <i>330</i> FEET FROM THE <i>N</i> LINE AND <i>2310</i> FEET FROM THE <i>W</i> LINE, SECTION <i>10</i> TOWNSHIP <i>21-S</i> RANGE <i>36-E</i> NMPM.	10. Field and Pool, or Wildcat <i>Oil Center Blinberry</i>
15. Elevation (Show whether DF, RT, GR, etc.) <i>3583 DF</i>	12. County <i>Lea</i>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

We propose to workover well as follows:

- 1. Kill well w/ Brine.*
- 2. Pull tbg & pkr.*
- 3. Perforate 4 1/2" CSG from 5970-5974, 5986-5990, 6000-6006, 6012-6015, 6094-6098, 6106-6110' w/ 1 shot/ft.*
- 4. Rerun pkr & tbg.*
- 5. Acidize perfs w/ 3000gal, 15% NE acid in 3 Stages w/ Unibeads.*
- 6. Swab & return well to production.*

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *[Signature]* TITLE *Unit Head* DATE *2/20/70*

APPROVED BY *[Signature]* TITLE *Inspector* DATE

CONDITIONS OF APPROVAL, IF ANY: