

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. State E-1923
7. Unit Agreement Name
8. Farm or Lease Name Berry Comm.
9. Well No. 1
10. Field and Pool, or Wildcat Berry (Morrow Gas)
12. County Lea

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator TEXACO Inc.
3. Address of Operator P. O. Box 728 Hobbs, New Mexico 88240
4. Location of Well UNIT LETTER N , 554 FEET FROM THE South LINE AND 1821 FEET FROM THE West LINE, SECTION 7 TOWNSHIP 21-S RANGE 34-E NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 3768' (DF)

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:


REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>


17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TEXACO Proposes To Do The Following Work On Subject Well:

- Kill well.
- Remove tree, install BOP, and unlatch packer.
- Spot following cement plugs:
from 13,860' - 13,570' w/50 sx Class "H" Cement.
from 12,600' - 12,485' w/20 sx Class "H" Cement.
Cut and Remove 7" (Approx. 10,000')
from 50' below-50' above casing cut w/40 sx Class "H" Cement.
from 5785'-5685' w/100 sx Class "C" Cement
20 sx Class "C" cement plug @ surface.
- Set 4" steel marker approximately 4' above ground level, clean location, and Abandon well.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED  TITLE Assistant District Superintendent DATE June 25, 1969

APPROVED BY  TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: _____