

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name	
2. Name of Operator Gulf Oil Corporation		8. Farm or Lease Name New Mexico F State	
3. Address of Operator Box 670, Hobbs, New Mexico 88240		9. Well No. 2	
4. Location of Well UNIT LETTER F , 1902 FEET FROM THE North LINE AND 1980 FEET FROM THE West LINE, SECTION 4 TOWNSHIP 21-S RANGE 35-E NMPM.		10. Field and Pool, or Wildcat Osudo Wolfcamp	
15. Elevation (Show whether DF, RT, GR, etc.)		12. County Lea	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐

OTHER **Plug and abandon** ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10,817' TD, 10,351' PB.

Pull tubing, rods and pump. Set CI BP at approximately 10,200' and cap with 2 sacks of cement. Cut and recover 5 1/2" casing from approximately 7500'. Spot 40 sack cement plug 50' inside 5 1/2" casing stub to 50' above stub and mud to 6200'; 40 sack cement plug from 6200' to 6100' and mud to 5350'; 40 sack cement plug from 5350' to 5250', across 9-5/8" intermediate casing set at 5298', and mud to 50'; 20 sack cement plug from 50' to surface. Clean location and install dry hole marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

ORIGINAL SIGNED BY
C. D. BORLAND

SIGNED _____

TITLE **Area Production Manager**

DATE **February 14, 1968**

APPROVED BY _____

TITLE _____

DATE _____

CONDITIONS OF APPROVAL, IF ANY: