

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department
OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240
DISTRICT II
P.O. Drawer 0d, Artesia, NM 88210
DISTRICT III
1000 Rio Brazos Rd., Aztec, Nm 87410

API NO. (assigned by OCD on New Wells) 30-025-22821
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. NA
7. Lease Name or Unit Agreement Name ARROWHEAD GRAYBURG UNIT
8. Well No. 101
9. Pool name or Wildcat ARROWHEAD GRAYBURG 3040

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator CHEVRON U.S.A. INC.
3. Address of Operator P.O. BOX 1150 ATTN: RORY MATTHEWS
4. Well Location Unit Letter B : 660 Feet From The NORTH Line and 1650 Feet From The EAST Line Section 25 Township 21 S Range 36E NMPM County
10. Elevation(Show whether DF, RKB, RT, GR, etc.) 3518' GL

11 Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CMT JOB <input type="checkbox"/>
OTHER: <input type="checkbox"/>	OTHER: ADD PERFS <input checked="" type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTER CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABAN. <input type="checkbox"/>

12. Describe Proposed or Completed Operations(Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

POOH WITH TBG. SET PACKER AT 3810' TEST CIBP TO 3000# OK.
PERFORATE 3767-70, 3746'-49', 3710'-18', 3693'-94', 3684'-85'.
SPOT ACID ON PERFS.
SWAB TEST, FRAC PERFS WITH 10,000 GALS OF GEL & 24,000# OF SAND.
CLEAN OUT HOLE.PERF @ 3790-3794, 3614-3817, 3821-3824, 3850-3856 & 3864-3866.
ABOVE PERFS SHOT WITH 3 1/8" GUNS, 2 JHPF, 180 DEG. PHSD.
ACIDIZED PERFS.
SWAB TESTED PERFS.RETURN WELL TO PRODUCTION.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Rory Matthews TITLE DRILLING TECH. DATE: 6/27/95

TYPE OR PRINT NAME RORY MATTHEWS TELEPHONE NO. (915) 687-7812

APPROVED BY Paul Kautz TITLE Geologist DATE JUL 03 1995

CONDITIONS OF APPROVAL, IF ANY: