

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
B-163	

**SUNDRY NOTICES AND REPORTS ON WELLS**

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator B. N. Muncy, Jr.	8. Farm or Lease Name Ica State
3. Address of Operator P.O. Box 196 Artesia, New Mexico 88210	9. Well No. #6
4. Location of Well UNIT LETTER <u>A</u> <u>833</u> FEET FROM THE <u>East</u> LINE AND <u>660</u> FEET FROM THE <u>North</u> LINE, SECTION <u>2</u> TOWNSHIP <u>21-S</u> RANGE <u>33-E</u> NMPM.	10. Field and Pool, or Wildcat Lynch-Yates Seven Rivers
15. Elevation (Show whether DF, RT, GR, etc.)	12. County Lee

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/> CHANGE PLANS <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Intend to plug and abandon well as follows:

1. Set 25 sack cement plug over perforation.
2. Cut off oil string at ree point, approximately 1000'.
3. Set 25 sack cement plug at casing cut off point.
4. Set 10 sack cement plug at surface.
5. Set dry hole marker.
6. Clean up location.

25 sacks base of 10 3/4 " c ss

24 hr. notice prior to setting plugs

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>[Signature]</u>	TITLE <u>Owner</u>	DATE <u>10-26-71</u>
APPROVED BY <u>Joe D. Ramsey</u>	TITLE <u>Dist. 1, Supr.</u>	DATE <u>DEC 27 1971</u>
CONDITIONS OF APPROVAL, IF ANY:		

RECEIVED

SEP 27 1971

OIL CONSERVATION COMM.  
HOBBS, N. M.