

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.B.	
LAND OFFICE	
OPERATOR	

10. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

7. Unit Agreement Name

2. Name of Operator
HANSON OPERATING COMPANY, INC.

8. Farm or Lease Name
KINGWOOD

3. Address of Operator
P. O. BOX #1515, ROSWELL, NEW MEXICO 88202-1515

9. Well No.
1

4. Location of Well
UNIT LETTER J 1780 FEET FROM THE South LINE AND 1650 FEET FROM THE East LINE, SECTION 25 TOWNSHIP 21S RANGE 36E NMPM.

10. Field and Pool, or Wildcat
Undes. Drinkard

15. Elevation (Show whether DF, RT, GR, etc.)
3546.4' GR

12. County
Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☒	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
FULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOB ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

Temporarily abandon Drinkard perforations by setting a Bridge Plug at 5230', Perforated interval 5196' - 5200' w/2 SPF and interval 5154' - 5128' w/2 SPF. (Glorietta) Acidize w/2000 gals 15% NEFE acid. Re-acidize w/6000 gals 15% gelled acid. Put well on production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Jaye Biswell TITLE Production Analyst DATE 09/23/85
ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT 1 SUPERVISOR
APPROVED BY DATE
SEP 25 1985

RECEIVED

SEP 24 1985

O.C.D.
HOBBS OFFICE