

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
NM 2512	

<p align="center">SUNDRY NOTICES AND REPORTS ON WELLS</p> <p align="center"><small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT..." (FORM C-101) FOR SUCH PROPOSALS.)</small></p>		
1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name	
2. Name of Operator	8. Farm or Lease Name	
Sohio Petroleum Company	Alves A	
3. Address of Operator	9. Well No.	
P.O. Box 3000, Midland, Texas 79701	2	
4. Location of Well	10. Field and Pool, or Wildcat	
UNIT LETTER <u>M</u> <u>660</u> FEET FROM THE <u>South</u> LINE AND <u>660</u> FEET FROM THE <u>West</u> LINE, SECTION <u>8</u> TOWNSHIP <u>21S</u> RANGE <u>37E</u> NMPM.	Penrose Skelly Grayburg	
15. Elevation (Show whether DF, RT, GR, etc.)	12. County	
3490 Gr.	Lea	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Pulled out of hole with tubing & set CIBP @ 3800' - capped with 35' of cement with dump bailer.
2. Run tubing and displaced casing with 9.5# mud laden fluid. Cut casing @ 2171 and POH.
3. Run tubing to 2176' and spotted 30 sack plug from 2176' to 2076'.
4. Pulled tubing to 1286' and spotted a 35 sack plug.
5. POH and cut off wellhead & spotted 5 sx surface plug.
6. Installed plate and Dry Hole marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Eddie W. Leary</u>	TITLE <u>District Superintendent</u>	DATE <u>5-15-77</u>
APPROVED BY <u>Eddie W. Leary</u>	TITLE <u>OIL & GAS INSPECTOR</u>	DATE <u>MAY 21 1977</u>
CONDITIONS OF APPROVAL, IF ANY:		