

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-7

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. CIL WELL ☒ GAS WELL ☐ OTHER- <u>Injector</u>	7. Unit Agreement Name NORTHEAST DRINKARD UNIT
2. Name of Operator SHELL WESTERN E&P INC. (4431 WCK)	8. Farm or Lease Name NORTHEAST DRINKARD UNIT
3. Address of Operator P. O. BOX 576, HOUSTON, TX 77001	9. Well No. 105
4. Location of Well UNIT LETTER <u>E</u> , <u>2080</u> FEET FROM THE <u>NORTH</u> LINE AND <u>660</u> FEET FROM THE <u>WEST</u> LINE, SECTION <u>3</u> TOWNSHIP <u>21S</u> RANGE <u>37E</u> N.M.P.M.	10. Field and Pool, or Wildcat NORTH EUNICE BLINEBRY- TUBB-DRINKARD OIL & GAS
15. Elevation (Show whether DF, RT, GR, etc.) 3486' DF	12. County LEA

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data.

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐

PLUG AND ABANDON ☐

CHANGE PLANS ☐

OTHER ☐

REMEDIAL WORK ☐
COMMENCE DRILLING OPERATIONS ☐
CASING TEST AND CEMENT JOBS ☐

OTHER OAP, AT / CTI ☒

ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

R-8541

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10-25-88 to 11-30-88:

POOH w/ prod equip. Perf Blinebry 5791' - 5823' and Tubb 6149' - 6199' w/ 1JSPF. Selectively AT Blinebry 5791' - 5823' and Tubb 6149' - 6199' w/ 1050 gals 15% NEFE HCl acid + 24 ball sealers each, using BP's and pkr's. (Total 2100 gals 15% NEFE HCl acid + 48 ball sealers). TIH w/ inj equip, setting Guiberson Uni-VI pkr @ 5734'. Pres test to 500 psi for 30 min - held O.K. Well began injecting 11-30-88.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED A. B. Curtis for A. J. FORE

TITLE SUPERVISOR REG. & PERMITTING

DATE DEC 21 1988

ORIGINAL SIGNED BY JERRY SEXTON

APPROVED BY DISTRICT 1 SUPERVISOR

TITLE

DATE DEC 30 1988

CONDITIONS OF APPROVAL, IF ANY:

E

RECEIVED

DEC 29 1988

ALL INFORMATION CONTAINED
HEREIN IS UNCLASSIFIED

HOBBS OFFICE

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-7

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. Unit Agreement Name NORTHEAST DRINKARD UNIT
2. Name of Operator SHELL WESTERN E&P INC. (4431 WCK)	8. Farm or Lease Name NORTHEAST DRINKARD UNIT
3. Address of Operator P. O. BOX 576, HOUSTON, TX 77001	9. Well No. 105
4. Location of Well UNIT LETTER E 2080 FEET FROM THE NORTH LINE AND 660 FEET FROM THE WEST LINE, SECTION 3 TOWNSHIP 21S RANGE 37E NMPM.	10. Field and Pool, or Wildcat NORTH EUNICE BLINEBRY-TUBB-DRINKARD OIL & GAS
11. Elevation (Show whether DF, RT, GR, etc.) 3486' DF	12. County LEA

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data.
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐

OTHER OAP, AT / CTI ☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPS. ☐
CASING TEST AND CEMENT JOB ☐
OTHER ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) POOH w/ prod equip.
- 2) Perf Blinebry 5791'-5794' w/ 1 JSPF and 5807'-5823' w/ 1 JSP2F. Perf Tubb 6149'-6166' w/ 1 JSPF and 6185'-6199' w/ 1JSP2F.
- 3) Selectively AT Blinebry 5791'-5823' and Tubb 6149'-6199' w/ 1050 gals 15% NEFE acid each, using BP's and pkrs. (2100 gals acid total).
- 4) Install injection equip, setting Guiberson Uni-VI pkr @ 5750'.
- 5) Press test to 300 psi for 30 min.
- 6) Turn well to injection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED A. J. FORE A. J. FORE

TITLE SUPERVISOR REG. & PERMITTING

DATE OCT 21 1988

Orig. Signed by
Paul Kautz
Geologist

APPROVED BY _____

TITLE _____

DATE OCT 24 1988

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

OCT 24 1988

CCC
HOBBS OFFICE