

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.B.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No.
K 5389

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Hunt Industries Ltd	8. Farm or Lease Name State 15
3. Address of Operator 600 W. Illinois, Suite 706; Midland, Tx 79701	9. Well No. #1
4. Location of Well UNIT LETTER N, 1980 FEET FROM THE West LINE AND 990 FEET FROM THE South LINE, SECTION 15 TOWNSHIP 21-S RANGE 35-E NMPM.	10. Field and Pool, or Wildcat South Osudo mallow
15. Elevation (Show whether DF, RT, GR, etc.)	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1/6/89 Run 7" CIBP, set @ 11,000 Cap w/25 sx on top of plug, Circ hole w/10# mud gel.
1/7/89 Set 25 sx plug - 7600 - 7463
1/7/89 Set 45 sx plug - 5550' Tag @ 5461 on 1/9/89
1/10/89 Set 50 sx plug - 5450' Tag @ 5340 on 1/11/89
1/11/89 Set 40 sx plug - 1800' - 1693'
1/11/89 Set 10 sx plug - 30' to surface
Cut well head off, install dry hole marker

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Sh. D. Lumber TITLE Cementer DATE 1/12/89

APPROVED BY R. A. Sudder TITLE OIL & GAS INSPECTOR DATE FEB 20 1989

CONDITIONS OF APPROVAL, IF ANY:

8

RECEIVED

JAN 26 1989

OCD
HOBBS OFFICE