

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
E - 1923

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER-	7. Unit Agreement Name
2. Name of Operator TXO Production Corp.	8. Farm or Lease Name South Wilson St Com
3. Address of Operator 900 Wilco Bldg, Midland, TX 79701	9. Well No. 1
4. Location of Well UNIT LETTER <u>J</u> <u>1800</u> FEET FROM THE <u>South</u> LINE AND <u>1980</u> FEET FROM THE <u>East</u> LINE, SECTION <u>1400</u> TOWNSHIP <u>21 S</u> RANGE <u>34E</u> NMPM.	10. Field and Pool, or Wildcat Wilson (Morrow)
15. Elevation (Show whether DF, RT, GR, etc.) 3702 KB 3700 DF 3680 GL	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input checked="" type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. *Notify Hobbs NMOCC at least 24 hrs before starting

Kill well
Unseat Pkr, TDH
Set CIBP @ 12600
TIH w/tbg & dump 20 sx or CIBP
Set 25 Sx @ 12300'
Set 25 Sx @ 11300'
Set 25 Sx @ 10400'
Set 25 Sx @ 8100'
Set 50 Sx from 5900-5500 (Tag TOC)
TDH W/tbg.
Free pt & cut 4 1/2" (TOC approx 5350)
TIH w/tbg. Set 50 Sx @ 4 1/2" stub & 50' into 8 5/8" (Tag TOC)
Set 50 Sx @ 3600
Set 50 Sx @ 1700
Set 10 Sx @ Surface

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Thrust Line Sff TITLE Production Engineer DATE 9-5-85

ORIGINAL SIGNED BY JERRY SEXTON

APPROVED BY DISTRICT 1 SUPERVISOR

TITLE _____ DATE SEP - 9 1985

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

SEP -6 1985

U.S. DEPT.
HOBBS OFFICE