

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-26666
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-158-3
7. Lease Name or Unit Agreement Name NM "BZ" State, 8817 JV-P
8. Well No. 1
9. Pool name or Wildcat Grama Ridge, NE Bone Springs

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator BTA Oil Producers	
3. Address of Operator 104 S. Pecos, Midland, TX 79701	
4. Well Location Unit Letter <u>N</u> : <u>730</u> Feet From The <u>South</u> Line and <u>2050</u> Feet From The <u>West</u> Line Section <u>26</u> Township <u>21S</u> Range <u>34E</u> NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3689' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Proposed Procedure:

- 1) Set CIBP @ 10050' w/35' cmt on top
- 2) Spot 50 sx cmt plug 7900-7700' (Cover "DV" tool @ 7837')
- 3) Spot 50 sx cmt plug 5800-5600' (Cover 10-3/4" shoe @ 5715')
- 4) Cut & pull 7-5/8" csg @ 600'
- 5) Spot 75 sx plug @ 475-375' (Cover 13-3/8" shoe)
- 6) Spot 30' plug @ surface
- 7) Install Dry Hole Marker

RECEIVED
JUL 10 1993
OIL CONSERVATION DIVISION
SANTA FE, N.M.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Royce D. Boyce TITLE Administrative Supervisor DATE 7-7-93
(915)

TYPE OR PRINT NAME Royce D. Boyce TELEPHONE NO. 682-3753

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE JUL 09 1993

CONDITIONS OF APPROVAL, IF ANY: