

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-26812
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Lansford
8. Well No. 4
9. Pool name or Wildcat Hare San Andres
10. Elevation (Show whether DF, RKB, RT, GR, etc.) GR. 3447

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER
2. Name of Operator Lanexco, Inc
3. Address of Operator 1105 West Kansas, Jal NM 88252
4. Well Location Unit Letter 0 : 810 Feet From The South Line and 1880 Feet From The East Line Section 21 Township 21S Range 37E NMPM Lea County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) GR. 3447

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data.

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: Squeeze perfs. Reperforate <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5-18-01 Squeeze Eumont perfs (3502-3607) with 100 sacks cement.

5-21-01 Drill out cement. Test squeeze to 500 PSI. Clean out to 4177'.

5-24-01 Perforate San Andres (3824-4114-16 holes .50). Acidize with 4000 gallon 15% Iron acid and 32 balls.

5-25-01 Swab test. Pull packer and put on production. Evaluate the well.

6-11-01 Run tubing pump to move more water and evaluate for further stimulation or larger pumping equipment.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE R.W. Lansford TITLE President DATE 6-26-01

TYPE OR PRINT NAME R.W. Lansford TELEPHONE NO. 505-395-30

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE 7/1/03

CONDITIONS OF APPROVAL, IF ANY:

Orig. Signed by
Paul Kuntz
Geologist

See CID3 3/3/03