

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501Form C-101
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

3A. Indicate Type of Lease
STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
5. State Oil & Gas Lease No.
L-5146

APPLICATION FOR PERMIT TO DRILL, DEEPEN, OR PLUG BACK

10. Type of Work

11. Type of Well

DRILL ☐DEEPEN ☐PLUG BACK ☒OIL WELL ☒GAS WELL ☐

OTHER

SINGLE ZONE ☒MULTIPLE ZONE ☐

12. Name of Operator

Texaco Producing Inc.

13. Address of Operator

P. O. Box 728, Hobbs, New Mexico 88240

14. Location of Well

UNIT LETTER T LOCATED 1980 FEET FROM THE South LINE

AND 660 FEET FROM THE West LINE OF SEC. 5 TWP. 21-S REC. 34-E NMPM

7. Unit Agreement Name

8. Farm or Lease Name

Berry 5 State Com.

9. Well No.

1

10. Field and Pool, or Wildcat

Berry Bone Springs, North

12. County

Lea

15. Elevations (Show whether DF, KT, etc.)

3731' GR

21A. Kind & Status Plug. Bond

Blanket

19. Proposed Depth

14,160' (TD)

19A. Formation

Bone Springs

20. Rotary or C.T.

Pulling Unit

22. Approx. Date Work will start

September 15, 1986

PROPOSED CASING AND CEMENT PROGRAM

SIZE OF HOLE	SIZE OF CASING	WEIGHT PER FOOT	SETTING DEPTH	SACKS OF CEMENT	EST. TOP
17-1/2"	13-3/8"	48#	1000'	835	Circulated
12-1/4"	9-5/8"	36# & 40#	5642'	1700	Circulated
8-1/2"	7"	26#	11,720'	1700	Circulated
6-1/8"	4-1/2"	13.5#	11,393-14,117'	500	Top of Liner

Well is currently completed in the Morrow with a PBTD of 13,530'. It will be plugged back to 13,265' and completed in the Bone Springs.

1. MIRU. Kill well. Remove wellhead and install BOP. Release packer and TOH.
2. Set 4-1/2" CIBP @ 13,300' with wireline. Dump 35' cement on top. New PBTD 13,265'.
3. Close BOP & pressure test well to 3400# for 30 minutes. If necessary, locate any leaks, squeeze with cement, drill out and retest.
4. GIH w/7" production packer & 2-3/8" production tubing. Circulate KCL water in perforation interval. Pull up hole, circulate packer fluid, set packer @ 8750'. Land tubing, ND BOP's and NU X-mas tree. Test X-mas tree & tubing to 3400#. Swab down tubing to 2000'.

Continued on Pg. 2

ABOVE SPACE DESCRIBE PROPOSED PROGRAM; IF PROPOSAL IS TO DEEPEN OR PLUG BACK, GIVE DATA ON PRESENT PRODUCTIVE ZONE AND PROPOSED NEW PRODUCTIVE ZONE. GIVE BLOWOUT PREVENTER PROGRAM, IF ANY.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

and L. J. Seeman Title Dist. Petr. Engr. Date 8/08/86

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON

DISTRICT SUPERVISOR

PROVED BY _____ TITLE _____ DATE AUG 11 1986

CONDITIONS OF APPROVAL, IF ANY: