Submit 3 Copies to Appropriate

APPROVED BY ---

CONDITIONS OF APPROVAL, IF ANY:

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103

Revised 1-1-89

| District Office | |
|--|---|
| DISTRICT I P.O. Box 1980, Hobbs, NM 88240 DISTRICT II P.O. Drawer DD, Artesia, NM 88210 OIL CONSERVATION DIVISION P.O. Box 2088 Santa Fe, New Mexico 87504-2088 | WELL API NO. 30-025-27439 |
| | 5. Indicate Type of Lease STATE FEE X |
| DISTRICT III 1000 Rio Brizos Rd., Aziec, NM 87410 | 6. State Oil & Gas Lease No. |
| | |
| SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) | |
| | M. L. Goins |
| 1. Type of Well: OIL GAS WELL X WELL OTHER | 8. Well No. |
| 2. Name of Operator | 8. Well No. |
| Kern Co. | 9. Pool name or Wildcat |
| 3. Address of Operator | |
| 3005 North Big Spring, Midland, Texas 79705 | Grayburg |
| 4 Wall Location | 330 Feet From The East Line |
| | NMPM Lea County |
| Section 7 Township 21S Range 37E 10. Elevation (Show whether DF, RKB, RT, GR, et al., 2495GL) | MARINI PEG |
| | Donat of Other Data |
| 11. Check Appropriate Box to Indicate Nature of Not | ice, Report, or Other Data |
| NOTICE OF INTENTION TO: | SUBSEQUENT REPORT OF |
| PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WO | RK X ALTERING CASING |
| TEMPORARILY ABANDON CHANGE PLANS COMMENCE D | RILLING OPNS. PLUG AND ABANDONMENT |
| PULL OR ALTER CASING CASING TEST | AND CEMENT JOB |
| OTHER: Plug San Andres for Grayburg X OTHER: Recompletion | in the of elasting any proposed |
| 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent datawork) SEE RULE 1103. | |
| 02-26-90 Blinebry zone plugged w/CIBP @ 35'+ cmt : Plug tested to 3000# and San Andres perfe | orated from 4134-51 w/8 |
| jet shots. San Andres produced 50+ bbl water per da | |
| on workover. | - |
| | |
| Proposed Grayburg Recompletion: Set CIBP @ 4110 and dump 4 sx (35'+) cmt | on top. |
| Test CIBP and casing to 3000#. | • |
| Perforate Grayburg zone w/13 jet shots f | rom 3763-3861. |
| Perforate Grayburg Zone w/15 jet Shoes z | 3 |
| Acidize perforations w/1500 gal NEA. | |
| Swab back load. | |
| Return to production and test. | |
| I hereby certify that the information above is true and complete to the best of my knowledge and belief. Fieldm | nan pate3-26-90 |
| SKINATURE TITLE | (915) TELEPHONE NO. 683–4832 |
| TYPEOR PRINT NAME Michael L. Wiberg | |
| (This space for State Use) Orig. Signs Paul Kau 2 | MAR 28 1990 |
| Geologist mue | DATE - |