| JERGY AND MINERALS DEP | | | |
|--|--|--|--|
| | CONSERVATION DIVISION | | |
| DISTRIBUTION | P. O. BOX 2088 | Form C-103 . | |
| SANTA FE | SANTA FE, NEW MEXICO 87501 | Revised 10-1-7 | |
| FILE | . SANTA PE, NEW MEXICO 87501 | | |
| U.S.Q.S. | · · · · · · · · · · · · · · · · · · · | 5a. Indicate Type of Lease | |
| LAND OFFICE | | State Tee X | |
| OPERATOR | | 5. State Off & Gas Lease No. | |
| | | | |
| IND MOT USE THIS FORM | SUNDRY NOTICES AND REPORTS ON WELLS FOR PROPOSALS TO DRILL ON TO DICEPEN OF PLUG BACK TO A DIFFERENT RESERVOIR. PPLICATION FOR PERMIT - (FORM CELOU) | | |
| en X well | OTHER- | 7. Unit Agreement Name | |
| ame of Operator | | 8. Farm or Lease liame | |
| Alpha Twenty-On | e Production Company | Lansford | |
| ddress of Operator | | 9. Well No. | |
| P.O. Box 1206, | Jal, NM 88252 | 6 | |
| ocation of Well | | 10. Field and Pool, or Wildcat | |
| •• | . 660 FEET FROM THE SOUTH LINE AND 990 FEET FR | | |
| UNIT LETTER P | FEET FROM THE SOULI LINE AND 990 FEET FR | • Penrose-Skelly | |
| East | s, section 21 township 21-S RANGE 37-E NAME | | |
| THE LINE | S, SECTION 21 TOWNSHIP 21-5 RANGE 37-E NMP | (| |
| mmm | 15. Elevation (Show whether DF, RT, GR, etc.) | 12. County | |
| | 3432.5' GL | Lea | |
| Minimum | | | |
| | heck Appropriate Box To Indicate Nature of Notice, Report of Control of Nature of Notice, Report of Control of Nature of Natur | | |
| NOTICE | OF INTENTION TO: SUBSEQUE | NT REPORT OF: | |
| | | · | |
| AFDAM REMEDIAL WORK | PLUG AND ABANDON REMEDIAL WORK | ALTERING CASING | |
| MPORARILY ABANDON | COMMENCE DRILLING OPHS. | PLUG AND ABANDOHMENT | |
| LE OR ALTER CASING | CHANGE PLANS CASING TEST AND CEMENT JOS | | |
| | OTHER Completion Att | empt x | |
| OTHER | | | |
| | | | |
| Describe Proposed or Complete work) SEE RULE 1103. | loted Operations (Clearly state all perfinent details, and give perfinent dates, includi | ng estimated date of starting any proposed | |
| | | | |
| 8-28-82 | Perforate the Grayburg section at the following depths: 3646, 3648, 3650, 3672, 3674, 3676, 3688, 3690, 3692, 3708, 3710, 3712, 3740, 3742, 3744, 3746, 3770, 3772, 3774, 3776, (20 Perforations). | | |
| . • | Spot 200 gals. 15% MCA acid over perfs; acidize with 15% MCA acid. Recovered load. | ith 4000 gals. | |
| 8-29-82 | Frac well down casing with 50,000 gals frac fluid sand. Had good show of oil and gas. | and 1080 sx | |
| | <i>,</i> ' | | |
| | | | |
| | | | |

| I hereby certify that the information bove in true and co | mplete to the best of my knowledge and belief. | | |
|---|--|-------------|---|
| 10 RW Jansford | V.P./Energy Resources | DATE 9-2-82 | |
| ORIGINAL SIGNED BY JERRY SEXTON | | SEP 3 1982 | E |
| OVED BY | YITLE | DATE | |

IDITIONS OF APPROVAL, IF ANY

63454456

SEP 2 1987

MOSS OFFICE