

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Free <input type="checkbox"/>
5. State Oil & Gas Lease No. LG-1022

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL <input checked="" type="checkbox"/> GAS <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator AMOCO PRODUCTION COMPANY	8. Farm or Lease Name State DV
3. Address of Operator P. O. Box 68, Hobbs, NM 88240	9. Well No. 1
4. Location of Well UNIT LETTER L 1980 FEET FROM THE South LINE AND 660 FEET FROM THE West LINE, SECTION 34 TOWNSHIP 21-S RANGE 35-E NMPM.	10. Field and Pool, or Wildcat Wildcat Wolfcamp
15. Elevation (Show whether DF, RT, GR, etc.) 3691.6' GL	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPERATIONS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to abandon subject well as follows:

Pull rods, pump, tubing and anchor. Set a cast iron bridge plug in 4-1/2", 13.5# casing at 10,600' and cap with 35' of cement. Spot 25 sacks of class C neat cement at 8000'. (Apx. 140' of cement) Spot 25 sacks of class C neat cement across casing shoe at 5650'. (This will place cement from 5720'-5580'.) Spot 25 sacks of class C neat cement across casing shoe at 811'. (This will place cement from 881'-741'). Spot 15 sack surface plug of class C neat cement. Erect PXA marker and cap well.

O+5-NMOCD, H 1-R. E. Ogden, HOU Rm. 21.150 1-F. J. Nash, HOU Rm. 4.206 1-CLF 1-Superior, Mid. 1-GDH, Bldg.

***Add Plugs as Follows:

100' plug @ top salt
100' plug @ base salt
Load hole w/10# salt gel

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Cathy L. Lorman</u>	TITLE <u>Assist. Admin. Analyst</u>	DATE <u>2-24-84</u>
APPROVED BY <u>Eddie W. Segy</u>	TITLE <u>Oil & Gas Inspector</u>	DATE <u>FEB 28 1984</u>

*****SEE ABOVE