

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.

5. Indicate Type of Lease
STATE FEE

6. State Oil & Gas Lease No.
V-37-1

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name
Charm State

1. Type of Well:
OIL WELL GAS WELL OTHER

8. Well No.
3

2. Name of Operator
John Yuronka

9. Pool name or Wildcat
Jalmar Yates 7 Rivers

3. Address of Operator
One Marienfeld Place, Ste 580, Midland, TX 79701

4. Well Location
Unit Letter p : 840 Feet From The South Line and 405 Feet From The East Line

Section 36 Township 21-S Range 35-E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3601' KB

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) POOH with rods & tubing
- 2) Set CIBP @ 3600 feet
- 3) RIH with W.S. - Circulate hole- Mix mud.
- 4) Spot 10 sacks of C cement on top of CIBP.
- 5) Spot 20 sacks of C cement @ 2000 feet.
- 6) Spot 20 sacks of C cement @ 450 feet.
- 7) Spot 10 sacks of C cement @ surface.
- 8) Cut off wellhead - Weld on dry hole marker -
R. Sadler OGC Witness - 4/8/92.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE President DATE 5/4/92

TYPE OR PRINT NAME Fred Newman (Triple "N" Services, Inc.) TELEPHONE NO (915)687-1994

(This space for State Use)
APPROVED BY [Signature] TITLE OIL & GAS INSPECTOR DATE JUL 14 '92

CONDITIONS OF APPROVAL, IF ANY: