

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-7

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. V-37-1	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER.		7. Unit Agreement Name
2. Name of Operator John Yuronka		8. Farm or Lease Name Charm State
3. Address of Operator 807 Petroleum Bldg., Midland, TX 79701		9. Well No. 3
4. Location of Well UNIT LETTER <u>P</u> <u>840</u> FEET FROM THE <u>South</u> LINE AND <u>405</u> FEET FROM <u>East</u> <u>36</u> TOWNSHIP <u>21-S</u> RANGE <u>35-E</u> NMPM.		10. Field and Pool, or Wildcat Jalmat
15. Elevation (Show whether DF, RT, GR, etc.) 3601' KB		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1109.

The following is the procedure for the proposed remedial work:

- Clean out to PBTD 3986'.
- Treat old perfs. 3812', 3819', 3830', 3836', 3838', 3923', 3924', 3925', & 3926' w/1500 gals. NeFe Acid.
- Perforate Yates 3675', 3696', 3709', 3726', 3732', 3734', 3736', 3743', 3748', 3750', 3768', & 3778 w/1 SPF & treat w/3000 gals. MCA Acid.
- Place well back on production to clean up for approx. 2 weeks.
- Frac w/15,000 gals. 2% KCl gel, 15,000 gals. CO₂ & 31,600# of sand.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED John Yuronka

TITLE Authorized Agent

DATE 6-6-85

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT 1 SUPERVISOR

TITLE _____

DATE _____

JUN 10 1985

CONDITIONS OF APPROVAL, IF ANY: