

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. <u>30-025-28857</u>
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name State L Com.
8. Well No. <u>2</u>
9. Pool name or Wildcat E. Grama Ridge-Morrow

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	
2. Name of Operator Pogo Producing Company	
3. Address of Operator P. O. Box 10340 Midland, Texas 79702-7340	
4. Well Location Unit Letter <u>F</u> : <u>1980</u> Feet From The <u>North</u> Line and <u>1980</u> Feet From The <u>West</u> Line Section <u>25</u> Township <u>21-S</u> Range <u>34-E</u> NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3649.8 GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Set CIBP @ 12,435' - dump 35' cement on same
Circulate mud laden fluid
Spot cement plug 10,663-863' - 100' in 5" liner, 100' in 7-5/8" casing
Cut and retrieve 7-5/8" at 8000'+
Spot 200' plug - 100' in stub, 100' in open hole - tag same
Spot 300' plug in 10-3/4" casing shoe at 5774' - 200' in casing - 100' in open hole - tag same
Spot 100' plug in 10-3/4" casing 3716 to 3816' (top of Capitan)
Spot 100' plug 1150 to 1250' in 10-3/4" - across surface pipe at 1200'
Spot 10 sx. cement in 10-3/4" at surface
Install P&A marker - cut anchors - clean surface

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE R. L. Wright TITLE Dist. Drlg. & Prod. Supt. DATE 6/5/89

TYPE OR PRINT NAME R. L. Wright TELEPHONE NO. 915/682-6822

(This space for State Use)

Orig. Signed by
Paul Kaatz
Geologist

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

THIS DOCUMENT IS NOT VALID FOR THE FIRST 24 HOURS AFTER THE SIGNATURE OF THE APPROVING OFFICIAL FOR THE O&G

JUN 13 1989