· · · · ·		\hat{f}_i	RC	oswell dig) ICT C	OPY	
Form 3160-5 (JUNE 1990) UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT " for such proposals						FORM APPROVED Budget Bureau No. 1004–0135 Expires: March 31, 1993 Lease Designation and Serial No. NM–14791 V If Indian, Allottee or Tribe Name	
SUBMIT IN TRIPLICATE					7.	If Unit or CA, Agreement Designation	
Gas Well Well X Other Plug and Abandon 2. Name of Operator STRATA PRODUCTION COMPANY						 Well Name and No. New Mexico A Federal #4 API Well No. 	
3. Address and Telephone No. P.O. Box 1030 Roswell, New Mexico 88202-1030 505-622-1127 4. Location of Well (Footage, Sec./T., R., M., or Survey Description)					127	30-025-30988 D. Field and Pool, or Exploratory Area Hat Mesa Delaware	
√1980' FNL & 660' FEL Section 4-21S-32E						Lea County, New Mexico	
CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA							
X Notice of J		X	Abandonment	TYPE OF ACTIO	<u>N</u>]	
Subsequer	nt Report		Recompletion Plugging Back			Change of Plans New Construction Non-Routine Fracturing	
Final Abar	ndonment Notice		Casing Repair Altering Casing OTHER		- (No	Water Shut – Off Conversion to Injection Dispose Water te: Report results of multiple completion cr. Well	
					Co	muletion or Recompletion Report and Las from	

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* on Report and Log form.)

Pursuant to Notice of Incidents of Noncompliance #AJM-045-98 dated 4/29/98, Strata Production Company proposes to plug and abandon the well in the following manner:

- 1. Set CIBP at 6700'. Place 35' of cement on top. Circulate hole with 9.5# per gallon mud.
- 2. Set First Plug at 3200'-3300' with 20 sacks Class "C" cement.
- 3. Set Second Plug at 1320'-1420' with 20 sacks Class "C" cement.
- 4. Set Surface Plug with 10 sacks Class "C" cement. Spot 9.5# per gallon mud between each plug.
- 5. Cut off wellhead, clean location and reclaim surface.

)

5. Cut off wellhead, clean location		SEE ATT CONDUTIONS	AGNER FOR Grandenal	
14. I hereby certify that the foregoing is true and correct				
Signed ADDAVED	Title Production Reco	rds Manager Da	ate6/1/98	
(This space for Federal or State office use)	RECE	TW/ IE IN		
Approved by	Title		ate	
Conditions of approved a strain SGD, DAVID R. GLASS		1998	11e	
Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly tatements or representations as to any matter within its jurisdiction.	and willfully to part to any department			
			ates any false, fictitious or fraudulent	
200 - 2017 EV EV EV EP *	See Instruction on Revers	e Side	F3	3160-5
GWW				



