Form 3160–5 (June 1990)	UNI: STATES DEPARTMENT OF I BUREAU OF LAND N	MANAGEMENT	HC H Budge I Bureau No. 1004-0135 Expires: March 31, 1903 5. Lease Designation and Serial No. NM 090162
Donotuse this form for prop Use "APPLICATION	SUNDRY NOTICES AND F posals to drill or to deepen or <u>I FOR PERMIT* for such p</u>	r reentry to a different reservoir.	6. If Indian, Allotise of Tribe Name
1. Type of Weil	SUBMIT IN TRIP	LICATE	7. If Unit or CA, Agreement Designation
X Oil Gas Weil Weil Ot 2. Name of Operator Ot	ther		8. Well Name and No. LOCKHART B 31
			WELL # 9 9. AP! Well No.
3. Address and Telephone No. <u>10 DESTA DR. STE 100W, MIDLAND, TX. 79705 (915) 686 - 5424</u> 4. Location of Weil (Footage, Sec., T., R., M., or Survey Description) SURFACE: 660' FNL & 1980' FWL, SEC. 31, T 21S, R 36E, UNIT LTR 'C' TD:			30 - 025 - 31637 10. Field and Pool, or Exploratory Area
			JALMAT TANSILL YATES 7 RVRS 11. County or Parish, State LEA, NM
12. CHECK APPROPRI	ATE BOX(s) TO INDICAT	E NATURE OF NOTICE, REP	
TYPE OF SUBMI	SSION	TYPE OF AC	TION
Notice of Intent	rt	Abandonment Recompletion Plugging Back Casing Repair	Change of Plans Change of Plans New Construction Non-Routine Fracturing Water Shut-Off
Final Abandonmer	nt Notice	Altering Casing	Conversion to Injection
4-26-95 MIRU. PO	OH W/ 2 3/8' TBG. GBIH W	X Other <u>PUT ON PUMP</u> Is, and give pertinent dates, including estimated rtical depths for all markers and zones pertinent t // 2 3/8* TBG SET @ 3940'.	Dispose Water (Note: Reportneyits of multiple completion on Well Completion or Recompletion Report and Log term.) date of starting any proposed work. If well is to this work.)*
4-26-95 MIRU. PO GIH W/ RODS & PUM	nace locations and measured and true ver OH W/ 2 3/8' TBG. GBIH W IP.	PUT ON PUMP Is, and give pertinent dates, including estimated rtical depths for all markers and zones pertinent t	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log term.)
4-26-95 MIRU. PO GIH W/ RODS & PUM	nace locations and measured and true ver OH W/ 2 3/8' TBG. GBIH W IP.	PUT ON PUMP Is, and give pertinent dates, including estimated rtical depths for all markers and zones pertinent t // 2 3/8' TBG SET @ 3940'.	(Note: Reportresults of multiple completion on Well Completion or Recompletion Report and Log form.) date of starting any proposed work. If well is to this work.)*
4-26-95 MIRU. PO GIH W/ RODS & PUM 4-28-95 RDMO. RE	TWE and correct	PUT ON PUMP Is, and give pertinent dates, including estimated rtical depths for all markers and zones pertinent t // 2 3/8" TBG SET @ 3940'. TION AS A PUMPING WELL.	(Note: Reportresults of multiple completion on Well Completion or Recompletion Report and Log term.) date of starting any proposed work. If well is to this work.)*
4-26-95 MIRU. PO GIH W/ RODS & PUM	TWE and correct	PUT ON PUMP Is, and give pertinent dates, including estimated rtical depths for all markers and zones pertinent t // 2 3/8' TBG SET @ 3940'. TION AS A PUMPING WELL. ACCEPTED FOR T ACCEPTED FOR T	(Not: Reportresults of multiple completion on Well Completion or Recompletion Report and Log form.) date of starting any proposed work. If well is to this work.)*

-

P

.

