

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
30-025-33986

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name

Zebra State

1. Type of Well:
OIL WELL ☐ GAS WELL ☐ OTHER

2. Name of Operator
Pogo Producing Company

8. Well No.
1

3. Address of Operator
P. O. Box 10340, Midland, TX 79702-7340

9. Pool name or Wildcat
Wildcat Bone Spring

4. Well Location
Unit Letter G : 1650 Feet From The North Line and 1650 Feet From The East Line

Section 16 Township 21S Range 32E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3736'

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Drilled 6-3/4" hole to 8900'. TD reached @ 0300 hrs CDT 7/27/97. Logged well with Western Atlas. Logs indicate poor reservoir. Pogo request permission to set plugs as per procedure below and P&A the above well based on recommendation via telephone with Charley Perrin with the NMOCD in Hobbs.

Spot 35 sxs Cl "C" cmt plug f/8740'-8640'
Spot 35 sxs Cl "C" cmt plug f/6720'-6120'
Spot 35 sxs Cl "C" cmt plug f/5540'-5440'
Spot 50 sxs Cl "C" cmt plug f/5100'-5000'
Set CIBP @ 4830'. Spot 540 sxs Cl "C" cmt plug f/4830'-1050'
Spot 25 sxs Cl "C" cmt plug f/25'-surface

Cut off wellhead and install P&A marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Barrett L. Smith TITLE Senior Operations Engineer DATE 8/12/97

TYPE OR PRINT NAME Barrett L. Smith (915)682-6822 TELEPHONE NO.

(This space for State Use) ORIGINAL SIGNED BY CHRIS WILLIAMS
DISTRICT I SUPERVISOR

APPROVED BY [Signature] TITLE Ed [Signature] DATE 3-19-03

CONDITIONS OF APPROVAL IF ANY:

DEC 08 1997