Submit-J Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

Form	C	-10	3
Revis	H	1-1	4

DISTRICT I P.O. Box 1980, Hobbs, NM 88	240
DISTRICT II P.O. Drawer DD, Artesia, NM	382

Form	C	-10	3
Revis	ьd	1-1	-8

DISTRICT I P.O. Box 1980, Hobbs, NM 88240 OIL CONSERVATION P.O. Box 2088	1 17 Linu 200 A 1 1 1 0 0	
1.C. DOX 2000		
DISTRICT.II Santa Fe, New Mexico 8 P.O. Drawer DD, Artesia, NM 88210	7504-2088 STATE XX FEE The state of Lease STATE XX FEE STATE XX FEE The state of Lease STATE XX FEE STATE XX FEE The state of Lease STATE XX FEE The state STAT	
DISTRICT III 1000 Rio Brazos Rd., Azzec, NM 87410	6. State Oil & Gas Lease No.	
SUNDRY NOTICES AND REPORTS ON WELL (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN O DIFFERENT RESERVOIR. USE "APPLICATION FOR PERI (FORM C-101) FOR SUCH PROPOSALS.)	PAR PLUG BACK TO A 7. Lease Name or Unit Agreement Name	
1. Type of Weil: On. GAS WELL WELL OTHER	Zebra State	
2. Name of Operator	8. Weil No.	
Pogo Producing Company	9. Pool name or Wildcat	
3. Address of Operator D. O. Boy 10240 Midland TV 70702 7240	Wildcat Bone Spring	
P. O. Box 10340, Midland, TX 79702-7340 4. Well Location	nii add o done, opi ing	
Unit Letter G: 1650 Feet From The North	Line and 1650 Feet From The East Line	
Section 16 Township 21S Rang	e 32F NMPM Lea County	
10. Elevation (Show whether Di		
11. Check Appropriate Box to Indicate N	ature of Notice Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON	REMEDIAL WORK ALTERING CASING	
TEMPCRARILY ABANDON CHANGE PLANS	COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT	
PULL OR ALTER CASING		
OTHER:	OTHER:	
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and work) SEE RULE 1103.		
reger regerroir Pogo reguest permi	hrs CDT 7/27/97. Logged well with Western Atlas ission to set plugs as per procedure below and P&A hone with Charley Perrin with the NMOCD in Hobbs.	
Spot 35 sxs Cl "C" cmt plug f/8740'-8640' Spot 35 sxs Cl "C" cmt plug f/6720'-6120' Spot 35 sxs Cl "C" cmt plug f/5540'-5440' Spot 50 sxs Cl "C" cmt plug f/5100'-5000' Set CIBP @ 4830'. Spot 540 sxs Cl "C" cmt Spot 25 sxs Cl "C" cmt plug f/25'-surface	·	
Cut off wellhead and install P&A marker. Thereby causy that the information above is rue and complete to the best of my knowledge and be	Senior Operations Engineer SATE 8/12/97	
SIGNATURE CAMER TITLE		
TYPEORPRINT NAME Barrett L. Smith	(915)682-6822 TELEPHONE NO.	
(Thus space for State Use) ODIGINAL GIGNED BY CHRIS WILLIAMS DERVISOR	DEC 08 1997	