Form 9-331 (May 1963) UN ED STATES UBMIT IN TRIPL 4TE* DEPARTMENT OF THE INTERIOR (Other Instructions on re- DEPARTMENT OF THE INTERIOR (Other Instructions on re- verse side) GEOLOGICAL SURVEY					NM - 02841	Budget Bureau No. 42-R142 5. LEASE DESIGNATION AND BERIAL NO NM - 02841		
	······				$\frac{1000}{6. \text{ IF INDIAN, ALLOTTE}}$	E OR TRIBE NA		
SUNDF (Do not use this for	The for property of the set of th	Sals to drill or to deepond of the permitted of the permi	ORTS ON en or plug back for such prop	N WELLS k to a different reservoir. osais.)				
l			······		7. UNIT AGREEMENF N.	AME		
OIL X GAS WELL	OTHER			·	8. FARM OR LEASE NA	<u></u>		
2. NAME OF OPERATOR			in a		Malco-Feder			
APCO Oil Corpor 3. ADDRESS OF OPERATOR	ation			<u> </u>	9. WELL NO.	<u></u>		
Liberty Bank Bu	uilding.	Oklahoma City	, Okla.	73102	• -1			
4. LOCATION OF WELL (Repo	ort location	clearly and in accordance	ce with any St	ate requirements.*	10. FIELD AND POOL, C	· · · · · · · · · · · · · · · · · · ·		
See also space 17 below.) At surface 2310' from South Line and 330' from East Line of Section 1,					Jalmat-Yate			
				e of Section 1,	11. SEC., T., B., M., OR SURVEY OR ARE	A		
T-23S, R-35E, I	lea Cour	nty, New Mexico			Sec.1,T-23S,R	- 35E		
14. PERMIT NO.		15. ELEVATIONS (Show	w whether DF, R	T, GR, etc.)	12. COUNTY OB PARIS	the second se		
11. IDADII NO.		31	+85' (GR)		Iea	New Me		
		Pau Ta	Indicato Na	ture of Notice, Report, or	Other Data	7 . 3 .		
16.					EQUENT REPORT OF:			
NOT	TICE OF INTE				REPAIRING	WELL		
TEST WATER SHUT-OFF		PULL OR ALTER CASING		WATER SHUT-OFF FRACTURE TREATMENT	ALTERING			
FRACTURE TREAT		MULTIPLE COMPLETE ABANDON*	X	SHOOTING OR ACIDIZING	ABANDONM			
SHOOT OB ACIDIZE Repair well		CHANGE PLANS		(Other)				
(Other)	<u> </u>			Completion or Reco	lts of multiple completion mpletion Report and Log f	orm.)		
17. DESCRIBE PROPOSED OR CO	OMPLETED O	PERATIONS (Clearly state tionally drilled, give sub	e all pertinent osurface locatio	details, and give pertinent dat ns and measured and true ver	tes, including estimated da tical depths for all marke	ite of starting rs and zones i		
nent to this work.) *								
proposed that	it be a	abandoned in t	he follow	nd is non-commercia ving manner:				
		plug over perf			ascing			
2. Shoot off	approx	imately 1,000'	of 14# 5	3690-3718'. 5 ¹ 2" OD production (casing.			
 Shoot off Place a 2 	approx 5 sack j	imately 1,000' plug in the $5\frac{1}{2}$	of 14# 5 " stub	$5\frac{1}{2}$ " OD production of				
 Shoot off Place a 29 Cement 4" 	approx 5 sack surfac	imately 1,000' plug in the $5\frac{1}{2}$ e marker in 8-	of 14# 5 " stub 5/8" OD s	$5\frac{1}{2}$ " OD production of surface casing with	h 10 sack plug			
 Shoot off Place a 29 Cement 4" 	approx 5 sack surfac	imately 1,000' plug in the $5\frac{1}{2}$ e marker in 8-	of 14# 5 " stub 5/8" OD s	$5\frac{1}{2}$ " OD production of surface casing with	h 10 sack plug			
 Shoot off Place a 29 Cement 4" 	approx 5 sack surfac	imately 1,000' plug in the $5\frac{1}{2}$ e marker in 8-	of 14# 5 " stub 5/8" OD s	$5\frac{1}{2}$ " OD production of	h 10 sack plug			
 Shoot off Place a 29 Cement 4" 	approx 5 sack surfac	imately 1,000' plug in the $5\frac{1}{2}$ e marker in 8-	of 14# 5 " stub 5/8" OD s	$5\frac{1}{2}$ " OD production of surface casing with	h 10 sack plug			
 Shoot off Place a 29 Cement 4" 	approx 5 sack surfac	imately 1,000' plug in the $5\frac{1}{2}$ e marker in 8-	of 14# 5 " stub 5/8" OD s	$5\frac{1}{2}$ " OD production of surface casing with	h 10 sack plug			
 Shoot off Place a 29 Cement 4" 	approx 5 sack surfac	imately 1,000' plug in the $5\frac{1}{2}$ e marker in 8-	of 14# 5 " stub 5/8" OD s	$5\frac{1}{2}$ " OD production of surface casing with	h 10 sack plug			
 Shoot off Place a 29 Cement 4" 	approx 5 sack surfac	imately 1,000' plug in the $5\frac{1}{2}$ e marker in 8-	of 14# 5 " stub 5/8" OD s	$5\frac{1}{2}$ " OD production of surface casing with	h 10 sack plug			
 Shoot off Place a 29 Cement 4" 	approx 5 sack surfac	imately 1,000' plug in the $5\frac{1}{2}$ e marker in 8-	of 14# 5 " stub 5/8" OD s	$5\frac{1}{2}$ " OD production of surface casing with	h 10 sack plug			
 Shoot off Place a 29 Cement 4" 	approx 5 sack surfac	imately 1,000' plug in the $5\frac{1}{2}$ e marker in 8-	of 14# 5 " stub 5/8" OD s	$5\frac{1}{2}$ " OD production of surface casing with	h 10 sack plug	(1) A set of the se		
 Shoot off Place a 29 Cement 4" Verbal approva 	approx 5 sack surfac al obta	imately 1,000' plug in the $5\frac{1}{2}$ e marker in 8- ined from the	of 14# 5 " stub 5/8" OD s	$5\frac{1}{2}$ " OD production of surface casing with	h 10 sack plug			
 Shoot off Place a 29 Cement 4" Verbal approve 	approx 5 sack surfac al obta	imately 1,000' plug in the 5 ¹ / ₂ e marker in 8- ined from the	of 14# 5 " stub 5/8" OD s Hobbs Dis	5 ¹ / ₂ " OD production o	h 10 sack plug h 14, 1969.	ch 14, 19		
 Shoot off Place a 29 Cement 4" Verbal approve 18. I hereby certify that find the signed of the state of the signed of the second seco	approx 5 sack surfac al obta	imately 1,000' plug in the $5\frac{1}{2}$ e marker in 8- ined from the s is true and correct	of 14# 5 " stub 5/8" OD s	5 ¹ / ₂ " OD production o	h 10 sack plug h 14, 1969.	ch 14, 19		
 Shoot off Place a 29 Cement 4" Verbal approve 	approx 5 sack surfac al obta	imately 1,000' plug in the $5\frac{1}{2}$ e marker in 8- ined from the s is true and correct	of 14# 5 " stub 5/8" OD s Hobbs Dis	5 ¹ / ₂ " OD production o	h 10 sack plug h 14, 1969. on DATE Mar	ch 14, 19		
 Shoot off Place a 29 Cement 4" Verbal approve I hereby certify that fill BIGNED 5.R. Live (This space for Federa APPROVED BY 	approx 5 sack surfac al obta he Xoregoing Say al or State	imately 1,000' plug in the 5 ¹ / ₂ e marker in 8- ined from the r is true and correct	of 14# 5 " stub 5/8" OD s Hobbs Dis	5 ¹ / ₂ " OD production o	h 10 sack plug h 14, 1969.	ch 14, 19		
 Shoot off Place a 29 Cement 4" Verbal approve 18. I hereby certify that find the space for Federal for Federa for Federal for Federa for Federal for Federa for Federal f	approx 5 sack surfac al obta he Xoregoing Say al or State	imately 1,000' plug in the 5 ¹ / ₂ e marker in 8- ined from the r is true and correct	of 14# 9 " stub 5/8" OD s Hobbs Dis TITLE Mgr.	5 ¹ / ₂ " OD production o	h 10 sack plug h 14, 1969. on DATE Mar	ch 14, 19		

1.

•