

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPPLICATE
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42 R1424.

5. LEASE IDENTIFICATION AND SERIAL NO.

NMP No. NM 04465

6. IF INDIAN, ALLOTTEE OR TRUST NAME

7. UNIT AGREEMENT NAME

Federal James

8. FARM OR LEASE NAME

2

9. WELL NO.

Triste Draw Delaware

10. FIELD AND POOL, OR WILDCAT

Sec. 35, T 23 S, R 32 W

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

12. COUNTY OR PARISH

Lea

13. STATE

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. NAME OF OPERATOR P-M Drilling Company	
3. ADDRESS OF OPERATOR 2900 N. Big Spring, Midland, Texas 79701	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface Federal James No. 2 Lea County, New Mexico 660'FNL and 1980'FEL Sec. 35	
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3685.4 GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☒CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☒(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE UNFINISHED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

7-24-76 Pulled rods and tubing

7-25-76 Muddied hole. Set CIBP @ 4585' and dumped 35' of cement on top of plug.

7-31-76 Cut 4 1/2" casing @ 3110'. Lay down casing.

8-2-76 Ran tubing to 3110'. Spotted 35 sx cement @ 3110' to 3010'; pulled up and spotted 35 sx cement 1200' to 1100'; pulled up and spotted 35 sx cement 375' to 275' and spotted 10 sx cement 15' to 0'. Welded plate over surface and installed dry hole marker.

Note: Will clean up surface as instructed.

18. I hereby certify that the foregoing is true and correct

SIGNED

J. H. McLean

TITLE

Owner-Operator

DATE

August 30, 1976

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

*See Instructions on Reverse Side