

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

COPY TO O.C.C. FILE

5. LEASE DESIGNATION AND SERIAL NO.

LC 068404(a)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Continental Oil Company

3. ADDRESS OF OPERATOR

P. O. Box 460, Hobbs, New Mexico 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

660' FSL and 3300' FEL of Sec 30

14. PERMIT NO.

16. ELEVATIONS (Show whether DF, RT, GR, etc.)

3517' df

7. UNIT AGREEMENT NAME

Bell Lake

8. FARM OR LEASE NAME

Bell Lake Unit

9. WELL NO.

2

10. FIELD AND POOL, OR WILDCAT

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec 30, T-235, R-34E

12. COUNTY OR PARISH 13. STATE

Lea N. Mex

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) Convert to SWD ☒PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☒REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)

It is proposed to ^{plug back and} convert the above well to saltwater disposal by the following procedures. Authority to perform this work was granted under Administrative Order SWD-119.

Pump 36 sacks class "C" high sulfate resistant cement from 8590' to 8390' Go in and cut 7" csg at $\pm 7450'$. Pull 7" casing. Run tubing to top of 7" casing stub and spot 50 sacks of high sulfate resistant cement above csg stub. Pull tbg out of cement & circulate out material left behind casing. (See attachment)

18. I hereby certify that the foregoing is true and correct

SIGNED

Arthur R. Browne

TITLE

Administrative Supervisor

DATE

8-25-71

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

USGS (5) File

Bell Lake Unit Partner

*See Instructions on Reverse Side

APPROVED

AUG 27 1971

ARTHUR R. BROWNE
DISTRICT ENGINEER

RECEIVED

AUG 5 1971

OIL CONSERVATION DIVISION
HISSE, D. L.