

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPL
(Other Instructions on Re-
verse side)

Budget Bureau No. 1004-0135
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

LC-030133B

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐
2. NAME OF OPERATOR
Conoco Inc.
3. ADDRESS OF OPERATOR
P.O. Box 460 - Hobbs, New Mexico 88240
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface
660' FNL & 1980' FFL - Unit Letter B

7. UNIT AGREEMENT NAME
South Eunice Unit
8. FARM OR LEASE NAME
South Eunice Unit
9. WELL NO.
36
10. FIELD AND POOL, OR WILDCAT
Eunice 7 River Queen S
11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA
28-22S-36E

14. PERMIT NO.
30-025-09077
15. ELEVATIONS (Show whether DF, RT, GR, etc.)

12. COUNTY OR PARISH
Lea
13. STATE
NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
(Other) CO Open Add'l Pay & Acidize ☒
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
ABANDON* ☐
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐
FRACTURE TREATMENT ☐
SHOOTING OR ACIDIZING ☐
(Other) ☐
REPAIRING WELL ☐
ALTERING CASING ☐
ABANDONMENT* ☐
(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

- 1) MIRR, POOH w/ rods & pump. Tag for fill w/ Hg & tally out of hole.
- 2) Clean well out to 3820'. POOH. Run CSG scraper to 3800'. POOH.
- 3) Perforate 3720'-3731' w/ 4 JSPF for total of 20 shots & POOH.
- 4) Set pkr at 3550'. Acidize w/ 150 bbls 15% HCL-NE-FE acid inhibited for 24 hrs at 100°F and 600 # graded rock salt mixed in 5 bbls gelled 9" brine in 3 equal stages. Flush w/ 80 bbls 9" brine. Swab well.
- 5) Release pkr at 3550' & POOH.
- 6) Land SN at 3766'. Run pump & rods and hang well on.

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature] D. FINNEY TITLE Administrative Supervisor

DATE 9/15/88

This space for Federal or State office use)

APPROVED BY [Signature] DATE 9/22/88

TITLE

DATE 9/22/88

CONDITIONS OF APPROVAL, IF ANY:

*See instructions on Reverse Side

Violation of this regulation makes it a crime for any person knowingly and willfully to make to any department or agency of the Department of the Interior, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

BLM-Sublet (1), Lease (2) Amend (2) Chevron (1) File

RECEIVED