

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☐ GAS WELL ☐ OTHER <u>Injection Well</u>	7. Unit Agreement Name <u>South Eunice Unit</u>
2. Name of Operator <u>Conoco Inc.</u>	8. Farm or Lease Name <u>South Eunice Unit</u>
3. Address of Operator <u>P.O. Box 460 - Hobbs, New Mexico 88240</u>	9. Well No. <u>51</u>
4. Location of Well UNIT LETTER <u>D</u> , <u>660</u> FEET FROM THE <u>north</u> LINE AND <u>660</u> FEET FROM THE <u>west</u> LINE, SECTION <u>33</u> TOWNSHIP <u>22S</u> RANGE <u>36E</u> NMPM.	10. Field and Pool, or Wildcat <u>Eunice 7 Rves Quaternary</u>
15. Elevation (Show whether DF, RT, CR, etc.)	12. County <u>Lea</u>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☒	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER <u>Replug Required</u> ☐	CASING TEST AND CEMENT JOBS ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

- Remove P&A marker & install wellhead on 7 5/8" csq.
- MIRU. Call NMOC & inform of operations. Drill out cement to 480'. Displace w/10" brine mud w/60-70 seconds/1000 cc funnel viscosity 5 cc or less water loss & 160-170,000 chlorides. P.O.O.H.
- Attempt to mill through collapsed csq at 480' & cement inside 4 1/2" csq to 700'. If successful circulate hole clean to 700' & P.O.O.H. If mill will not stay inside csq to 700' P.O.O.H. & G.I.H. w/5 7/8" washover shoe & pipe. Washover 4-5' its csq, cut & remove. Repeat until csq is removed to below collapse section 500'. P.O.O.H. Clean out to RBP at 700' & P.O.O.H.
- G.I.H. w/on-off tool & 2 7/8" tbg. Release RBP at 700' & set at 3600'. Pump 25 sx class "C" cement from 3600' - 3250'. Displace w/19 bbls 10" mud. P.O.O.H. to 3100' & pump 125 sx class "C" cement from

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED DF Finney TITLE Administrative Supervisor DATE February 3, 1988

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT SUPERVISOR

APPROVED BY _____ TITLE _____ DATE FEB 8 - 1988

CONDITIONS OF APPROVAL, IF ANY:

nmocn - This (3) arcd (2) amocd (2) C'ment (1) Lbl.

REC'D
FEB 5 1988
HOBBS OFFICE

South Eunice Unit #51
Pg 2.

3100' - 1400' to cover salt section. Displace w/ 8
bbls 10# mud. POOH to 700'. Pump 100 sxs class
"C" from 700' to surface. POOH & fill hole to
surface w/ cement.

⑤ Rig down & remove wellhead.

⑥ Cut csg 3' below ground level. Install P&A marker.

If you have any questions, please contact
Jay Vashler at 393-4141.

RECEIVED

FEB 5

OCC

1938

HOBBS OFFICE