

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State ☐	Fee ☒
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. Unit Agreement Name <i>South Eunice Unit</i>
2. Name of Operator <i>Conoco Inc.</i>	8. Farm or Lease Name <i>South Eunice Unit</i>
3. Address of Operator <i>P.O. Box 460 - Hobbs, New Mexico 88240</i>	9. Well No. <i>53</i>
4. Location of Well UNIT LETTER <i>B</i> , <i>660</i> FEET FROM THE <i>North</i> LINE AND <i>1480</i> FEET FROM THE <i>East</i> LINE, SECTION <i>33</i> TOWNSHIP <i>22S</i> RANGE <i>36E</i> NMPM.	10. Field and Pool, or Wildcat <i>Eunice 7 Rvrs Queens</i>
15. Elevation (Show whether DF, RT, GR. etc.)	12. County <i>Dea</i>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER <i>Clean Out, Open Adit Pay & Stimulate</i> ☒	CASING TEST AND CEMENT JOBS ☐	OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) MIRR. POOH w/ rods & pump. Tag for fill w/ hq & tally out of hole.
- 2) Clean well out to 3850'. Run csq scraper to 3850' & POOH.
- 3) Log well from 3850'-3400'. Correlate to the open hole, log & POOH.
- 4) Perforate 3648'-3736' w/ 4 jsp F for total of 112 shots & POOH.
- 5) Set treating pk at 3500'. Acidize w/ 120 bbls 15% HCL-FE acid w/ 84 gals Checker-Sol or equivalent inhibited for 24 hrs at 100°F and 600# graded rock salt mixed in 5 bbls gelled 9# Brine in 3 equal stages. Flush w/ 80 bbls 9# Brine. Swab well. Release pk at 3500' & POOH.
- 6) Land SN at 3800'. Run pump & rods. Place on test. For further information contact Jay Vashler at 397-5866.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *[Signature]* *DF FINNEY* TITLE *Administrative Supervisor* DATE *9/15/88*

ORIGINAL SIGNED BY JERRY SEXTON

APPROVED BY *[Signature]* *DISTRICT 1 SUPERVISOR* TITLE DATE

CONDITIONS OF APPROVAL, IF ANY:

1980' FEL & 660' FML
 Sec 33, T-22S, R-36E
 Elev: 3481' DF; 0: 10' AGL

Completion History:

9-17-59: Perf 3630'-3798'
 Frac w/4000 gals acid +
 20,000 gals oil + 1st gals d
 3-8-74: Pump chg
 2-28-80: Lofr MA in hole
 9-23-85: Pump chg

8⁵/₈" 24[#] J-55
 @ 316' w/225 sx
 (Circ)

Top Salt: 1440'
 Base Salt: 3015'
 Yares: 3112'
 TR: 3386'
 Queen: 3790'

2³/₈" +bg w/SN @ ±3800'
 OEMA @ 3832'

MA in hole e?

DOD: 3900'

TD: 3920'

3630'-38'
 3696'-3706'
 3742'-56'
 3790'-98'
 4 JS PF

4¹/₂" 9.5[#] J-55 @ 3920' w/1800 sx (Circ)

Made by JDL
 Checked By
 Date 9-3-87
 Page 1

Company No.
 Calculation Sheet

Title South Eunice Unit No 53
 Present

Job No.
 Drawn NMMFV
 State NM