

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. B-1506

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator ARCO. Oil and Gas Company Division of Atlantic Richfield Company	8. Farm or Lease Name Seven Rivers Queen Unit
3. Address of Operator P. O. Box 1710, Hobbs, New Mexico 88240	9. Well No. 48
4. Location of Well UNIT LETTER <u>D</u> <u>660</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM THE <u>West</u> LINE, SECTION <u>3</u> TOWNSHIP <u>23S</u> RANGE <u>36E</u> N.M.P.M.	10. Field and Pool, or Wildcat Langlie Mattix 7Rivers
15. Elevation (Show whether DF, RT, GR, etc.) 3494' GR	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

RU, POH w/rods & pump. Install BOP & POH w/tbg. DO CIBP @ 3800'. RIH w/pkr, spot acid across perfs 3814-22', set pkr @ 3775' & acidize w/2000 gals 15% NEA acid. If non-commercial, perf 3761-64, 3768-72, 3780-86, 3792-94, 3800-3810' = 30 holes. Spot 100 gals acid across perfs 3761-3810'. Set pkr @ 3630' & acidize w/6000 gals 15% NEA acid, flush w/2% KCL wtr. Frac w/19,500 gals 40# x-linked gel & 24,500# 20/40 sd & 32,000# 10/20 sd, flush w/2% KCL wtr. Swab test, CO sd & RIH w/tbg, rods & pump, return to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Roland P. Lawrence TITLE Drllg. Engr. DATE 9/8/82APPROVED BY Eddie W. Sney TITLE OIL & GAS INSPECTOR DATE SEP 13 1982

CONDITIONS OF APPROVAL, IF ANY: