

Form 551
(May 1967)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPlicate
(One to Bureau, one to State, one to local office)

FIELD OFFICE
Project Number No. 42 1111
5. FIELD DESIGNATION AND BUREAU NO.
10-0305570
6. INDIAN, ABBOT OF TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL ☐ GAS ☐ **M** OTHER ☐
2. NAME OF OPERATOR
Continental Drilling Company
3. ADDRESS OF OPERATOR
P.O. Box 460, Dallas, Texas 75201
4. LOCATION OF WELL (Give location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface
**1980' FSL and 660' FSL, Sec. 5, T-23S,
R-31E, Run County, N.M.**
14. PERMIT NO.
DE 5478
15. ELEVATIONS (Specify whether FH, RT, or GL, etc.)
DE 5478

7. UNIT ACQUISITION NAME
MMFL
8. FARM OR LEASE NAME
Survey A-5
9. WELL NO.
2
10. FIELD AND PUG, OR WILDCAT
Survey A-5
11. TOWN, T. 1. N., R. 1. E., S. 1. N.
Sec. 5, T-23S, R-31E
12. COUNTY OF FURNISH
Run
13. STATE
N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

ACTION OF INTENTION TO:		SUBSEQUENT REPORT OF:			
TEST WATER SHUT-OFF	☐	WATER SPURGE	☐	REPAIRING WELL	☐
FRACURE LOG	☐	FRACURE TREATMENT	☐	ALTERING CASING	☐
SHOOT OR ACIDIZE	☐	SHOOTING OR ACIDIZING	☐	ABANDONMENT*	☐
REPAIR WELL	☐	(Other)	☐		
(Other)	☐	(Other)	☐		

(Never report results of multiple completion on Well Completion or Report, Report and Log (CML))

17. INDUSTRY PRODUCTION OR COMPLETION OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all depths and record parts from this work.)

This well is presently classified as a shut-in. Gabeit
from well. It is proposed to drill out below the
present completion and test the upper 7-1/2' zone
fracture. Spurge perfor (3327-3464') upper ok close
"C" cement w/5th salt + 3rd sand per ok. Drill out
plug to cont. returns (3630'). Run GR/W and
collar logs. Perf selected zone 04 shots from 3570-3630'.
as log perf. zone w/500 gal. 15% LSTNT
with 600 returns. Soak to remove acid.
Install pumping unit and produce.

18. I hereby certify that the foregoing is true and correct

SIGNED _____ TITLE **Administrative** DATE **11-19-78**

(This space for Bureau or State office use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

DECS-5
MMFL 4
8-10-1

*See Instructions on Reverse Side