

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE
(Other instructions on
reverse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ Salt water disposal Temporarily shut-in

2. NAME OF OPERATOR
CONOCO INC.

3. ADDRESS OF OPERATOR
P. O. Box 460, Hobbs, N.M. 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface Unit G

14. PERMIT NO.
1980' FNL & 1980' FEL
30-025-09266

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

5. LEASE DESIGNATION AND SERIAL NO.

LC-030557(a)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

NMFU

8. FARM OR LEASE NAME

Farney A-S

9. WELL NO.

5

10. FIELD AND POOL, OR WILDCAT

Talbot Yates seven Rivers

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

sec. 5-235-36E

12. COUNTY OR PARISH

Lea

13. STATE
NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other) Plug and abandon

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

MIRV. GIH to CIBP @ 3611'. Pump 5 sx class "C" cmt. from 3611' to 3564'. POOH to 1000' & spot 11 sx class "C" cmt from 1000' to 900'. POOH to 350' & spot 11 sxs class "C" cmt from 350' to 250'. POOH to 50' & spot 6 sx class "C" cmt from 50' to surface. Cut off casing 3' below surface. Weld 1/4" metal cover over wellbore. Install abandonment marker. This notice pursuant to verbal approval per Pete Chester w/ BLM-Roswell on 9-9-85.

18. I hereby certify that the foregoing is true and correct

Administrative Supervisor

SIGNED

TITLE

DATE 9-9-85

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE 10-27-85

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side