Haven & ##fa	Form Approved.	
Form 9-381 a. (Feb. 1961)	(SUBMIT IN TRIPLICATE) UNITED STATES DEPARTMENT OF THE INTERIOR 3 UT 0 GEOLOGICAL SURVEY	

SUNDRY NOTICES AND REPORTS ON WELLS

Farney A-5 Well No. 7 is located W/4 SE/4 Sec.5 (% Sec. an.i Sec. No.)		nd 1650 ft. from E line NHPM (Meridian) New Mexic	
Well No. 7 is located	23-8 36-E	NNPM	e of sec. 5
Well No. 7 is located		ad1650 ft. from $\left\{ \begin{array}{c} E \\ \hline x \\ x \\$: of sec. 5
	Octob	per 2	, <u>19</u> 6
(INDICATE AD	OVE BY CHECK MARK NATURE OF REPO	IRT, NOTICE, OH OTHER DATA)]
NOTICE OF INTENTION TO PULL OR ALTER NOTICE OF INTENTION TO ABANDON WELL	¥	TARY WELL HISTORY	
NOTICE OF INTENTION TO SHOOT OR ACID	IZESUBSEQUEN	T REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO RE-DRILL OR RI	1	IT REPORT OF RE-DRILLING OR REPAI	1 1
NOTICE OF INTENTION TO TEST WATER SH		T REPORT OF ALTERING CASING	1 1
	SUBSEQUEN	NT REPORT OF WATER SHUT-OFF NT REPORT OF SHOOTING OR ACIDIZIN	NG

The elevation of the derrick floor above sea level is 3469 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and langths of proposed casings; indicate mudding jobs, cement-Studies performed on this well conclude that remedial work to return the well to a producing status cannot be justified.

We now propose to plug and abandon in the following manner:

- Set 150' Cmt plug (20 sx) from 3800' to 3650'.
 Cut and pull approx. 1150' of 5½" casing.
 Fill csg w/10 lb mud and set 20 sx cmt plug at top of 5½" csg.
- Set 10 sx cmt plug at surface. 4.
- Erect 4" marker extending 4' above surface with well name and location 5. inscribed thereon. Restore location to original condition.

A subsequent report will be filed upon completion of this work.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced. Company Continental Oil Company Address Box 68 - Eunice, New Mexico USGS-5 NHOCC-2 ABS File Bv PAN AM-HES-3 ATL-HOSW-2 Title District Superintendent CALIF OIL-HOUS, MID - 1 each.

GPO 914974

Budent Damage No. 43-D151 4