

D. Erect an abandonment marker according to the following specifications:

1. Marker must be at least 4" diameter pipe, 10' long with 4' above restored ground level, and embedded in cement.
2. Marker must be capped and inscribed with the following well information:

Steven B No. 3
Unit D, Sec. 12, T-23S, R-36E
Lea County, NM
Date

Note: 1/4" metal plate can be welded to marker and then to the casing after the marker is set in cement.


- E. Cut off dead-man anchors below ground level and remove markers. Fill in cellar and workover pit.
- F. Remove all equipment, concrete bases, and pipe not in use.
- G. Clean and restore location to its natural state. Reseed according to BLM requirements.

6. Send a copy of the well service report to the Division office so the proper forms can be filed.

Approved:


Production Specialist

5-23-90
Date


Engineer


5-24-90
Date


Supervising Production Engineer

5/24/90
Date


Division Engineering Manager

5/30/90
Date


Production Superintendent

5/31/90
Date

RECEIVED

JUN 27 1990

CCO
HOBBS OFFICE