STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

we, or Corizo beceives	1	
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S,		
LAND OFFICE		
0555	1	

OIL CONSERVATION DIVISION

<u> </u>		.1				21011					
	PISTRIBUTION			P. O. BO	X 2088 .				orm C-103 -		
3 4 1	ITA FE		SAI	NTA FE. NE	W MEXICO 87	501		R	evised 10-1-78		
7:1		1-1-1		•			150	. Indicate Type of L			
	.0,1,						"	State	Foo X		
<u> </u>	AD OFFICE				•		-				
107		لسلسا	•*				3.	State Oil & Gas Le	ase No.		
					·			mmm	mm		
40		SUNDRY	NOTICES AND	REPORTS OF	WELLS						
1.	v3£ "	APPLICATIO	H FOR PERWIT -" IF	ORM C-101) FOR 31	CH PADPOSALS.)	THE SERVOIN.			777777777		
OIL	₹	\Box					7.	Unit Agreement Na	me		
9 11		<u> </u>	OTHER-			<u> </u>					
2. Name of							8.	8. Farm or Lease Name			
Marathon Oil Company								Walter Lynch			
3. Address	of Operator						9.	Well No.			
	P.O. Box 24	109 Ho	obbs, New Me	exico				5			
4. Location	n of Well				*	····	10	Field and Pool, o			
	C C	66	60	North	LINE AND 19	80	TA.		The control of the state of the		
UMIT	LETYER		FEET PROS	4 THE THE THE	LINE AND	00 FEET	FROM TO	rinkard	innin		
	77			_					:////////		
THE	west	KOITSSE , 3	т	ожизить2	2S RANGE	37F	имрм. 🦳		11111111		
mm	mmm	m	17777	(61) .1	Dr. Dr. cn			mmit	444444		
//////					r DF, RT, GR, etc.)		12	County			
777777	7777777777777777777777777777777777777	777777	71111 KB 33	62'; GR 33	50'			Lea N	77777777		
lė.		Check Ap	propriate Box	To Indicate	Nature of Notic	e, Report o	r Other	Data			
_			ENTION TO:		1			EPORT OF:			
	٠										
PERFORM R	EMEDIAL WORK		PLUG	HOCHABA DHA	REMEDIAL WORK		7	ALTERING C			
TEMPORAR	1LY ABAHDON			6	COMMENCE DRILLE	F	า์		. =		
	LYEN CABINE		£ 11.11	IGE PLANS	CASING TEST AND		1	PLUG AND A	THEMMODHA		
7000 04 21				VI. 75.443	ł		1				
		•		[1	a bradenne face.	<u> 280. Cot</u>	nections to	fhe X		
OTHER_	····			———— L_J	Sur	lace.			•		
17. Descrit	be Proposed or Com	pleted Open	ations (Clearly sta	te all pertinent de	tails, and give pertin	nent dates, incl	luding esti	mated date of starti	ne any proposed		
work)	5EE RULE 1103.				•		-	,	, , ,		
	1. Dug well	callar	out to own								
	T. Dag well	Cerrar	out to expo	ose casing	bradenhead ou	itlets.	,				
	2. Installe										
	2. Instatte	a 1 b1	ping from 2	valve on	each bradenhe	ead outlet	to a	point			
	above gr	ouna 1e	vel. Insta	lled l" val	ve on upper e	end of pip	oing.				
	1		_					•			
	3. Conducte	d brade	nhead pressu	ire survey.							
	,				•						
,	Piping a	rrangem	ent, open po	osition of	lower valve a	and closed	posit	ion of			
	valve ab	ove gro	und level, i	inspected a	nd approved b	y NMOCD D	eputy	Oil & Gas			
	Inspecto	r, Davi	d Catanach.								
									•		
						Bradenhe	ad				
	Brade	enhead	Size		Ţ	alve Loca					
					<u> </u>	are been					
		13 3/8		•	North Side o	of wellher	d (E2	at Value \			
		8 5/8			North Side of						
					TOTEL PIGE O	'r werrnea	.ч (we	er sarse)			
					•				•		
								· · · · · · · · · · · · · · · · · · ·			
18. I hereby	certify that the info	da neilacmo	ove is true and con	aplete to the best	of my knowledge and	i belief.					
_	7/1./ 1	/	. /						v		
SIGNED	Theke De	Respor	igh	TITLE Ens	rineering Tec	hnician		DATE 5-17-8	3		
			/								
		11/1/11	1	\bigcirc	IL & GAS [MCDE(~r)	ar	MAVa) 40		
. PPBOYED B1	,Down	d Coke	innek_		u a and L	7 167 L TIOT (<u> </u>	DATE WHI ZE	3 1983		

MAY 20 1983