

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-101  
Effective 1-1-65

*Correct*

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
37721	

## SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Exxon Company, USA	8. Farm or Lease Name Paddock Unit
3. Address of Operator P.O. Box 2183 Hobbs, New Mexico	9. Well No. 13
4. Location of Well UNIT LETTER <u>A</u> . <u>660</u> FEET FROM THE <u>N</u> LINE AND <u>660</u> FEET FROM THE <u>E</u> LINE, SECTION <u>2</u> TOWNSHIP <u>22S</u> RANGE <u>37E</u> NMPM.	10. Field and Pool, or Wildcat PADDOCK
15. Elevation (Show whether DF, RT, GR, etc.) 3366 DF	12. County Lea

### Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

### 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4-14-83 Mix and pump 30 sack plug @ 5100'. WOC.  
4-15-83 Could not tag plug.  
4-15-83 Mix and pump 30 sack plug @ 5100'. WOC.  
4-18-83 Tag plug @ 4982'. Circulate hole with mud.  
4-18-83 Spot 30 sacks of cement @ 3900'.  
4-18-83 Spot 30 sacks of cement @ 2860'.  
4-19-83 Perforate @ 1250'. Set packer @ 950'. Pump 200 sacks of cement to surface.  
4-20-83 Tag plug @ 1144'.  
4-20-83 10 sacks for surface plug with plate and marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED E. F. Lowe TITLE SR. ADMIN. DATE 5-10-83  
APPROVED BY Ellen W. Long (HAP) TITLE OIL & GAS INSPECTOR DATE AUG 10 1983  
CONDITIONS OF APPROVAL, IF ANY: