

NO. OF COPIES RECEIVED		
DISTRIBUTION		
DATE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

<p align="center">SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</p>		<p>5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/></p> <p>5. State Oil & Gas Lease No.</p>
<p>1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-</p> <p>2. Name of Operator Amerals Hess Corporation</p> <p>3. Address of Operator Drawer "D", Monument, New Mexico 88265</p> <p>4. Location of Well UNIT LETTER A , 990 FEET FROM THE East LINE AND 660 FEET FROM North THE 4 LINE, SECTION 22-S TOWNSHIP 37-E RANGE 37-E NMPM.</p>		<p>7. Unit Agreement Name</p> <p>8. Farm or Lease Name H. Corrigan</p> <p>9. Well No. 11</p> <p>10. Field and Pool, or Wildcat Brunson Ellenburger</p>
<p>15. Elevation (Show whether DF, RT, GR, etc.)</p>		<p>12. County Lea</p>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plan to: Set CIBP at approx. 7345'. Run Gamma Ray Neutron log from 2700' to 7345'. Perforate Abo zone subject to logs. Acidize and swab test. If non-commercial set BP and perforate Paddock zone. Swab test. If necessary acidize, and frac. Run production equipment and restore well to producing status.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *M. B. Black* TITLE **EMERGENCY** Supver. Admin. Serv. DATE **2-28-75**

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY: