Submit 3 Copies to Appropriate

State of New Mexico

Energy, Minerals and Natural Resources Department

Form C-103

to Appropriate		gy, Millerais and Natural Resour	· · · · · · · · · · · · · · · · · · ·			Revised 1-1-89		
District Office	Olf	L CONSERVATION D	IVISION					
		P.O. Box 2088						
DISTRICT I		Santa Fe, New Mexico	87504-2088					
P.O. Box 1980, Hobbs, NN	A 88240	Santa 1 c, 14cvv Mexico	07304-2000					
DISTRICT II	, 652 16			API NO. (assigne	d by OCD on New Well	(s)		
P.O. Drawer DD, Artesia, NM 88210					30-025-10661 108A1			
DISTRICT III				5. Indicate Type		<u> </u>		
1000 Rio Brazos Rd., Azte	c, Nm 87410				STATE	FEE X		
				6. State Oil & Ga	as Lease No.			
	SUNDRY NOTIC	ES AND REPORTS ON WEL	LS					
(DO NO		SALS TO DRILL OR TO DEEPEN OF		7. Lease Name or Unit Agreement Name				
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"								
	(FORM C-101) FO	OR SUCH PROPOSALS.)		LEE STEBBINS NCT-B				
1 Type of Well:	CAS							
OIL .	GAS	OTHER						
WELL	WELL X	OTHER						
2 Name of Operator	Jahralassan laa			8. Well No.	2			
3 Address of Operator	Petroleum, Inc.			9. Pool name or	3			
	wlor St. Suita II A. Et V	Jorth Toyas 75102		BLINBRY	_			
4 Well Location	ylor St., Suite II-A, Ft. V	TOTAL TEXAS TOTAL		DEINDKI	Blinep	<u>, cy</u>		
Unit Letter A	(\)	660 Feet From The NORTH	Line and	46	0 Feet From The	EAST Line		
Section	5 -	Township T22S	Range	37E	_	EA County		
		10. Elevation(Show whether D	F, RKB, RT, GR, etc.)					
		3464' GL						
11	Check Appropriate	Box to Indicate Nature of Notice, Repo	ort, or Other Data					
NOTIC	E OF INTENTION TO:	•	SUBSEQUENT R	EPORT OF:				
PERFORM REMEDIAL WO	ORK X PLUG AND ABAND	ON REMEDIAL W	ORK	7	ALTERING CASING	; <u> </u>		
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS.				-	PLUG AND ABAND	ON H		
		-	AND CMT JOB	=	. 2001			
PULL OR ALTER CASING			AND CM1 JOB			_		
OTHER		OTHER:						
			• • •					
	Completed Operations(Clearly state og any proposed work) SEE RULE 11	all pertinent details, and give pertinent date	s, including					
WE PROPOSE:	ig any proposed work) SEE NOLE 11	33.						
WE FROFUSE.								
SET C	IBP @ 6025' CAPPED W	/2 SX CMT. TO ABANDON T	HE TUBB COMPLE	TION, SET CI	.BP @			
5695' (CAPPED W/2 SX CMT TO	DABANDON THE LOWER B	LINEBRY COMPLE	TION. PERFO	ORATE			
UPPER	R BLINEBRY FROM 5490	'-5566'. ACIDIZE USING PP	PKR., FRAC TREA	AT., FLOW BA	CK AND			
	ON PRODUCITON.		,	,				
1 5 102	. ON TRODUCTION							

	ation above is true and complete to the be		edge and belief.			
SIGNATURE	uni Brooks	TITLE	PRODUCTION ANALYST	DATE:	5/10/95	
TYPE OR PRINT NAME BOBBIE BROOKS				TELEPHONE NO. (915)685-1961		
	Orig. Signed by, Paul Kautz				BERT A LANGE	
APPROVED BY	Geologist	TITLE		DATE	113 1/135	
CONDITIONS OF APPROVAL	, IF ANY:					