	3 ⁷ 11	
NO OF COPIES RECEIVED		Form C-103
DISTRIBUTION		Supersedes Old
SANTAFE	NEW MEXICO OIL CONSERVATION COMMISS	C-102 and C-103 ION Effective 1-1-65
FILE		Cites (148 1-1-0)
U.S.G.S.		Sa. Indicate Type of Leuse
LAND OFFICE		Strite Fee X
OPERATOR		5. State Oil & Gas Lease No.
······································	· ·	of oreits of a cap Davide his.
SUNDRY		<u> </u>
(DO NOT USE THIS FORM FOR PROP USE "APPLICATIC	Y NOTICES AND REPORTS ON WELLS POSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESE ON FOR PERMIT _ " (FORM C-101) FOR SUCH PROPOSALS.)	ervoir. ())))))))))))))))))))))))))))))))))))
Ι.	(COM CITOT) FOR SICH PROPUSALS.)	7, Unit Agreement Name
WELL XX WELL	OTHER-	
2. Name of Operator		8. Farm or Leane Barrie
Gulf Oil Corporation	Lee Stebbins (NCT-B)	
3. Address of Operator		9. Well No.
Paul 670 Habba Nove Ma	aut op 98240	
Box 670, Hobbs, New Me	4 10. Field and Pool, or Wildcat	
R (1)	(0 Nambh 1700	
UNIT LETTER	50 FEET FROM THE NOTTH LINE AND 1780	FEET FROM Drinkard
-	r 00 a 07 m	
THE <u>East</u> line, section	TOWNSHIP 22-S RANGE 37-E	ММРМ. ())))))))))))))))))))))))))))))))))))
///////////////////////////////////////	15. Elevation (Show whether DF, RT, GR, etc.)	
		12. County
	3450' GL	Lea
Check A	ppropriate Box To Indicate Nature of Notice, R	eport or Other Data
NOTICE OF INT		UBSEQUENT REPORT OF:
		<u> </u>
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	COMMENCE DRILLING OP	NS. PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMEN	арь ті
	OTHER	
OTHER Perforate addition		
and acidize and fr	tac treat.	
work) SEE RULE 1103,	rations (Clearly state all pertinent details, and give pertinent d	ates, including estimated date of starting any proposed
6585' TD.		
Pull producting of	winment Porforate 7 ¹¹ casing in Drin	kard zong in the conrevingto

Pull producing equipment. Perforate 7" casing in Drinkard zone in the approximate interval 6370' to 6500'. Run treating equipment. Treat new perforations and open hole interval 6509' to 6585' with approximately 3,000 gallons of 15% NE acid and frac treat with 10,000 gallons of gel brine and 25,000 of gel brine containing 1 to 2# SPG. Flush with gel brine water. Pull treating equipment. .Run 2-3/8" tubing and packer. Set packer at approximately 6300'. Swab and clean up and return well to production.

8. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

غد

IGNED	Byfarking		TITLE Area Engineer	DATE January 17, 1975
		······································		
PPROVED BY			TITLE	
	S OF APPROVAL, IF ANY:	- <u>2</u> +		DATE

L

JAN 2

UIL CONSERVATION CHIM. HOBBS, N. M.