Submit 3 Copies to Appropriate E District Office	State of Ne ine Minerals and Nati	aral Resources Department	,	Form C-103 Revised 1-1-89
	DIL CONSERVA	TION DIVISION	WELL API NO.	
P.O. DOX 1980, HODDS, INM 88240	P.O. Bo	x 2088	3002510104	1
DISTRICT II P.O. Drawer DD, Artesia, NM 88210	Santa Fe, New Me	exico 87504-2088		-
			5. Indicate Type of Lease Federal ST	
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil & Gas Lease N	
SUNDRY NOTIC	ES AND REPORTS ON	WELLS		
(DO NOT USE THIS FORM FOR PROP DIFFERENT RESERVE	DSALS TO DRILL OR TO DE DR. USE "APPLICATION R 1) FOR SUCH PROPOSALS	EEPEN OR PLUG BACK TO A	7. Lease Name or Unit Age	eement Name
1. Type of Well:		<u>~</u>	C.P. Falby "A	" Federal
OL GAS WELL XX WELL	OTHER			
2. Name of Operator			8. Well No.	
Texaco Inc. 3. Address of Operator			9. Pool name or Wildcat	
P.O. Box 730 Hobbs, Net	/ Mexico 88240		9. Pool name or Wildcat Eumont Yates	7-R-0
4. Well Location			······································	
Unit Letter \underline{D} : $\underline{660}$	_ Feet From The No	rth Line and	660 Feet From The	West Lin
Section 8	Township 22S	Range 37E	NMPM	Lea County
	10. Elevation (Show 1	whether DF, RKB, RT, GR, etc.) 3443 [†] DF		
11. Check Aj	ppropriate Box to Ind	icate Nature of Notice, I		
NOTICE OF INTE	INTION TO:	SU	BSEQUENT REPO	RT OF:
		1		
				1
	PLUG AND ABANDON			ING CASING
	PLUG AND ABANDON CHANGE PLANS			
				ING CASING AND ABANDONMENT
		COMMENCE DRILLI		
		COMMENCE DRILLI		
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLI CASING TEST AND OTHER: Casing	NG OPNS. PLUG. CEMENT JOB Connections	AND ABANDONMENT
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLI CASING TEST AND OTHER: Casing	NG OPNS. PLUG. CEMENT JOB Connections	AND ABANDONMENT
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLI CASING TEST AND OTHER: Casing	NG OPNS. PLUG. CEMENT JOB Connections	AND ABANDONMENT
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLI CASING TEST AND OTHER: Casing	NG OPNS. PLUG. CEMENT JOB Connections	AND ABANDONMENT
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLI CASING TEST AND OTHER: Casing OTHER:	NG OPNS. PLUG CEMENT JOB Connections	AND ABANDONMENT
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLI CASING TEST AND OTHER: Casing etails, and give pertinent dates, inc	NG OPNS. PLUG CEMENT JOB Connections	AND ABANDONMENT
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Operation work) SEE RULE 1103. 4-5-91 1. Cellar dug out. 2. Placed riser on 13" Placed riser on 9 5/	CHANGE PLANS	COMMENCE DRILLI CASING TEST AND OTHER: Casing etails, and give pertinent dates, inc	NG OPNS. PLUG CEMENT JOB Connections Unding estimated date of starting	and ABANDONMENT
TEMPORARILY ABANDON	CHANGE PLANS os (Clearly state all persiment d surface casing ar 8" intermediate c urface casing and	COMMENCE DRILLI CASING TEST AND OTHER: Casing etails, and give pertinent dates, inc	NG OPNS. PLUG CEMENT JOB Connections Unding estimated date of starting	and ABANDONMENT
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Operation work) SEE RULE 1103. 4-5-91 1. Cellar dug out. 2. Placed riser on 13" Placed riser on 9 5/ Placed riser on 7" s 3. Filled cellar back i	CHANGE PLANS surface casing ar 8" intermediate of urface casing and n.	COMMENCE DRILLI CASING TEST AND OTHER: Casing etails, and give pertinent dates, inc d brought to surfat asing and brought brought to surfat	NG OPNS. PLUG CEMENT JOB Connections duding estimated date of starting ce with valve and ot surface with v e with valve and	AND ABANDONMENT
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Operation work) SEE RULE 1103. 4-5-91 1. Cellar dug out. 2. Placed riser on 13" Placed riser on 9 5/ Placed riser on 7" s	CHANGE PLANS surface casing ar 8" intermediate of urface casing and n.	COMMENCE DRILLI CASING TEST AND OTHER: Casing etails, and give pertinent dates, inc d brought to surfat asing and brought brought to surfat	NG OPNS. PLUG CEMENT JOB Connections duding estimated date of starting ce with valve and ot surface with v e with valve and	AND ABANDONMENT
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Operation work) SEE RULE 1103. 4-5-91 1. Cellar dug out. 2. Placed riser on 13" Placed riser on 9 5/ Placed riser on 7" s 3. Filled cellar back i Work inspected by R.A.	CHANGE PLANS Surface casing and "intermediate of urface casing and n. Sadler of the OCI	COMMENCE DRILLI CASING TEST AND (OTHER: Casing etails, and give pertinent dates, inc d brought to surfa asing and brought d brought to surfac	NG OPNS. PLUG CEMENT JOB Connections duding estimated date of starting ce with valve and ot surface with v e with valve and	AND ABANDONMENT
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Operation work) SEE RULE 1103. 4-5-91 1. Cellar dug out. 2. Placed riser on 13" Placed riser on 9 5/ Placed riser on 7" s 3. Filled cellar back i	CHANGE PLANS surface casing an 8" intermediate of urface casing and n. Sadler of the OCI and complete to the best of my known	COMMENCE DRILLI CASING TEST AND O OTHER: Casing etails, and give pertinent dates, inc d brought to surfat asing and brought d brought to surfac bo before the cellar	NG OPNS. PLUG CEMENT JOB Connections Unding estimated date of starting ce with valve and ot surface with v e with valve and was filled back	AND ABANDONMENT
TEMPORARILY ABANDON	CHANGE PLANS as (Clearly state all pertinent d surface casing and "intermediate c urface casing and n. Sadler of the OCI and complete to the best of my know	COMMENCE DRILLI CASING TEST AND (OTHER: Casing etails, and give pertinent dates, inc d brought to surfa asing and brought d brought to surfac	NG OPNS. PLUG CEMENT JOB Connections Conne	and ABANDONMENT any proposed marker alve marker. marker. in. marker.
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Operation work) SEE RULE 1103. 4-5-91 1. Cellar dug out. 2. Placed riser on 13" Placed riser on 9 5/ Placed riser on 7" s 3. Filled cellar back i Work inspected by R.A.	CHANGE PLANS as (Clearly state all pertinent d surface casing and "intermediate c urface casing and n. Sadler of the OCI and complete to the best of my know	COMMENCE DRILLI CASING TEST AND O OTHER: Casing etails, and give pertinent dates, inc d brought to surfat asing and brought d brought to surfac bo before the cellar	NG OPNS. PLUG CEMENT JOB Connections Conne	AND ABANDONMENT
TEMPORARILY ABANDON	CHANGE PLANS as (Clearly state all pertinent d surface casing and "intermediate c urface casing and n. Sadler of the OCI and complete to the best of my know	COMMENCE DRILLI CASING TEST AND O OTHER: Casing etails, and give pertinent dates, inc d brought to surfat asing and brought d brought to surfac bo before the cellar	NG OPNS. PLUG CEMENT JOB Connections Conne	and ABANDONMENT any proposed marker alve marker. marker. in. marker.
TEMPORARILY ABANDON Image: Complete Proposed or Completed Operation work) PULL OR ALTER CASING Image: Complete Proposed or Completed Operation work) 12. Describe Proposed or Completed Operation work) SEE RULE 1103. 4-5-91 Image: Complete Proposed or Completed Operation work) 4-5-91 Image: Complete Proposed or Complete Operation work) 4-5-91 Image: Complete Proposed or Complete Operation Proposed or Complete Operation Proposed or Complete Operation Proposed Operation Properation Properation Properation Proposed Operation Properation P	CHANGE PLANS as (Clearly state all pertinent d surface casing and "intermediate c urface casing and n. Sadler of the OCI and complete to the best of my know	COMMENCE DRILLI CASING TEST AND O OTHER: Casing etails, and give pertinent dates, inc d brought to surfat asing and brought d brought to surfac bo before the cellar	NG OPNS. PLUG CEMENT JOB Connections Connections duding estimated date of starting ce with valve and ot surface with v e with valve and was filled back Assistant DA	and ABANDONMENT any proposed marker alve marker. marker. in. marker.