

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease  
State ☐ Fee ☒  
5. State Oil & Gas Lease No

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator EXXON CORPORATION	8. Farm or Lease Name J. L. GREENWOOD
3. Address of Operator P.O. BOX 1600, MIDLAND, TEXAS 79701	9. Well No. 1
4. Location of Well UNIT LETTER <u>P</u> <u>660</u> FEET FROM THE <u>SOUTH</u> LINE AND <u>660</u> FEET FROM THE <u>EAST</u> LINE, SECTION <u>9</u> TOWNSHIP <u>22-S</u> RANGE <u>37-E</u> NMPM.	10. Field and Pool, or Wildcat BLINEBRY
15. Elevation (Show whether DF, RT, GR, etc.) 3427 DF	12. County LEA

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

PULL TBG. RUN WORKSTRING TO 5770 AND SPOT 20 SX CEMENT PLUG,  
FILL WELL W/9.5#/GAL. MUD LADEN BRINE (25 SX GEL PER 100 BBLs. BRINE).  
SPOT 20 SX CEMENT PLUG AT 3900 TO 4000.  
SPOT 25 SX CEMENT PLUG AT 1650 TO 1750.  
SPOT 25 SX CEMENT PLUG AT 280 TO 380.  
SPOT 10' PLUG AT SURFACE AND SET STEEL MARKER.  
NOTE: PUMP ALL PLUGS DOWN W/9.5#/GAL. MUD LADEN BRINE.  
TAG ALL PLUGS TO VERIFY PLACEMENT

100' plugs in & out all stubs.

8 3/4" hole 7" CS 3547'

12 B.P.S. @ 4947' w/ 25X Cement on top

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>A. J. Clemmer</u>	TITLE <u>UNIT HEAD</u>	DATE <u>4-3-75</u>
APPROVED BY <u>John W. Remyer</u>	TITLE <u>Geologist</u>	DATE <u>7/1</u>
CONDITIONS OF APPROVAL, IF ANY:		