

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
2040 Pacheco St.
Santa Fe, 87505

WELL API NO.

30-025-10180

5. Indicate Type of Lease

STATE ☐

FEE ☒

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name

Brunson-Argo

1. Type of Well:

OIL
WELL ☒

GAS
WELL ☐

OTHER

2. Name of Operator

Titan Resources I, Inc.

8. Well No.

19

3. Address of Operator

500 W. Texas, Suite 500, Midland, Tx 79701

9. Pool name or Wildcat

Paddock

4. Well Location

Unit Letter E : 1980 Feet From The North Line and 760 Feet From The West Line

Section 10

Township 22-S

Range 37-E

NMPM

Lea

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3433 RKB

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☒

PLUG AND ABANDON ☐

REMEDIAL WORK ☐

ALTERING CASING ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

PULL OR ALTER CASING ☐

CASING TEST AND CEMENT JOB ☐

OTHER: Complete Additional Pay in Paddock ☒

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. MIRU Pulling Unit. POOH with rods, pump and tubing.
2. Run clean-out bailer and clean out to 5807 ft (PBTD).
3. Acidize perfs 5088'- 5206' with 3,500 gals 15% NEFe HCl.
4. Set retrievable bridge plug at 5070 ft. Perforate additional zone in Paddock from 5001' - 5021'; 5042' - 5048'.
5. Acidize with 2,500 gals 15% NEFe HCl.
6. Swab back load. Retrieve bridge plug.
7. Run tubing, pump and rods and put on production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Ron Lechwar

TITLE Project Manager

DATE 4/30/97

TYPE OR PRINT NAME

Ron Lechwar

TELEPHONE NO. (915) 682-6612

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT SUPERVISOR

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

MAY 02 1997

