

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.
7. Unit Agreement Name
8. Farm or Lease Name E. W. Walden
9. Well No. 2
10. Field and Pool, or Wildcat Penrose-Skelly
12. County Lea

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator ANADARKO PRODUCTION COMPANY
3. Address of Operator P. O. Box 806, Eunice, New Mexico 88231
4. Location of Well UNIT LETTER <u>F</u> <u>1980</u> FEET FROM THE <u>North</u> LINE AND <u>1980</u> FEET FROM THE <u>West</u> LINE, SECTION <u>15</u> TOWNSHIP <u>22-S</u> RANGE <u>37-E</u> N.M.P.M.
15. Elevation (Show whether DF, RT, GR, etc.) N.A.

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. RUPU & pulled tubing;
2. Ran 2-7/8" tubing to 3620';
3. Pumped 100 sks of Class "C" Neet cmt w/4% gel, 5# Gilsonite, & 1/4# Flocele per sack; pulled tubing, 4-28-76;
4. Ran tubing and tagged top cement at 3060';
5. Loaded casing with 10# salt gel mud;
6. Spotted 20 sks cement plugs at 2500', 1200', and 30 sk plug @ 300', 4-28-76;
7. Installed dry hole marker and removed anchors;
8. Cleaned and levelled location;
9. Location is now ready for inspection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Herb Anderson</u>	TITLE <u>Area Supervisor</u>	DATE <u>05/03/76</u>
APPROVED BY _____		
CONDITIONS OF APPROVAL, IF ANY:		