

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease  
State ☐ Fee ☒  
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <b>Nonproducing</b>	7. Unit Agreement Name
2. Name of Operator <b>Sohio Petroleum Company</b>	8. Farm or Lease Name <b>Amador Christmas "C"</b>
3. Address of Operator <b>P. O. Box 3167, Midland, Texas 79701</b>	9. Well No. <b>1</b>
4. Location of Well UNIT LETTER <b>H</b> <b>660</b> FEET FROM THE <b>E</b> LINE AND <b>1980</b> FEET FROM THE <b>N</b> LINE, SECTION <b>17</b> TOWNSHIP <b>22-S</b> RANGE <b>37-E</b> NMPM.	10. Field and Pool, or Wildcat <b>Penrose-Skelly</b>
15. Elevation (Show whether DF, RT, GR, etc.)	12. County <b>Lea</b>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Pump <sup>25</sup> 25 sx. cement 3619' to 3699', fill with heavy mud between cement plugs, 10 sx. cement from 3505' to 3465'. Pull all 7" casing possible; then pump 10 sx. cement from 1100' to 1132' (bottom of 8-5/8"). Put 5 sx. cement in top of 8-5/8" casing. Weld 4" diameter or larger steel marker to casing, to extend at least 4' above ground level with name of well, location as follows: H Sec. 17, T22S, R37E, Permanently engraved by stamping, welding or other means.

25 sx @ 7" stub  
25 sx @ Base of soft  
~~25 sx @ Top of soft~~  
25 " across 8 5/8" shoe  
10 sx @ surface

18. I hereby certify the information above is true and complete to the best of my knowledge and belief.

SIGNED (A. E. Hood) TITLE District Superintendent DATE March 1, 1968 4

APPROVED BY Joe L. Roney TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY: